Drainage Report

UPS Parcel Distribution Facility

21612460

Prepared for C2K Architecture 19800 Village Office Ct. #206 Bend, OR 97702

February 3, 2017





Document Information

Prepared for C2K Architecture

Project Name UPS Parcel Distribution Facility

File Reference 1246-Preliminary Drainage Report.docx

Job Reference 21612460

Date February 3, 2017

Contact Information

Cardno

5415 SW Westgate Drive, Suite 100 Portland, Oregon 97221

Telephone: 503-419-2500 Facsimile: 503-419-2600

Jim.Harper@cardno.com www.cardno.com

Document Control

Version	Date	Author	Author Initials	Reviewer	Reviewer Initials
1	February 03, 2017	Luis Giron	LAG	Jim Harper	JH

© Cardno 2014. Copyright in the whole and every part of this document belongs to Cardno and may not be used, sold, transferred, copied or reproduced in whole or in part in any manner or form or in or on any media to any person other than by agreement with Cardno.


This document is produced by Cardno solely for the benefit and use by the client in accordance with the terms of the engagement. Cardno does not and shall not assume any responsibility or liability whatsoever to any third party arising out of any use or reliance by any third party on the content of this document.


Table of Contents

1 VIC	CINITY MAP	4
2 PR	OJECT DESCRIPTION	5
2.1	Project Overview	5
3 PR	E-DEVELOPED CONDITIONS	5
3.1	Environmentally Sensitive Areas	5
3.2	Topography	5
3.3	Climate	6
3.4	Site Geology	6
3.5	Hydrology	6
	3.5.1 Onsite Hydrology	6
3.6	3.5.2 Offsite Hydrology Basin Areas	6
	ST-DEVELOPED CONDITIONS	6
4 FO 4.1	Hydrology	6
4.2	Basin Areas	7
	DROLOGIC ANALYSIS DESIGN GUIDELINES	7
5.1	Design Guidelines	7
5.2	Western Washington Hydrology Model	7
5.3	System Capacities	7
6 Wa	ter Quality	8
6.1	Water Quality Facility	8
7 Co	nveyance Analysis	9
8 Qu	alitative Downstream Analysis	10
9 SU	MMARY	17
Tables		
Table 3-1	Soil Characteristics	6
Table 3-2	Pre-Developed Basin Areas	6
Table 4-1	Post-Developed Basin Delineation Summary	7
Table 5-1	Flow Control Structure Geometry	7
Table 6-1	Water Quality Design	8
Table 6-2	Water Quality Capacity	9
Table 7-1	MRI Values	9
Table 7-2	Stormwater Flow Values for Sub-Basins	10
Table 7-3	Stormwater Flow Values for Sub-Basins	10
Figures		
Figure 1-1	Vicinity Map	4
Figure 5-1	Volume Curve for 84" Duromaxx	8

1 VICINITY MAP

Figure 1-1 Vicinity Map





2 PROJECT DESCRIPTION

2.1 Project Overview

United Parcel Service is proposing construction of an additional parking lot for its parcel distribution facility to be located on the southeast corner of the NE Union Hill Rd. and 185th Ave NE intersection, See Figure 1-1. The site consists of approximately 3.27 acres zoned MP (Manufacturing Park).

The purpose of this report is to describe the stormwater management systems proposed as part of the new development and how they conform to water quality standards and regulations for the City of Redmond, King County and the Washington Department of Ecology. The total impact area for this development is approximately 2.65 acres.

The proposed storm improvements include collecting and conveying stormwater runoff from the proposed parking lot to an existing stormwater sewer located within 185th Ave NE Right-Of-Way. The proposed stormwater improvements will meet the required standards for the City of Redmond, King County, and the Washington Department of Ecology for stormwater quality, quantity, and conveyance. The existing stormwater infiltration pond is to remain with drainage patterns unchanged.

The conveyance detention standards for the City of Redmond, King County, and the Washington Department of Ecology have been meet by using the Western Washington Hydrology Model to model the stormwater runoff generation for proposed and existing conditions. All runoff from the proposed impervious areas will be conveyed to the existing 12-inch storm sewer pipe located within 185th Ave NE.

Contech Duromaxx steel reinforced polyethylene pipes will provide the necessary detention volume to keep post-development stormwater flows from exceeding pre-development flows. A BioClean Linear Modular Wetland vault is proposed to treat stormwater runoff from the proposed impervious areas downstream of the detention facility. The proposed water quality facility has general use level approval from the Washington Department of Ecology for basic and enhanced treatment types.

3 PRE-DEVELOPED CONDITIONS

3.1 Environmentally Sensitive Areas

The existing site does not have any wetlands mapped by the U.S. Fish and Wildlife Service National Wetlands Inventory. There is a Freshwater Emergent Wetland and A Freshwater Forested/Shrub Wetland approximately 0.1 miles northwest of the property. The general topography of 185th Ave NE and NE Union Hill Rd drains south away from the wetlands and they are likely to remain unaffected by drainage generated from proposed improvements. No threatened or endangered species are mapped by the U.S. Fish and Wildlife Service Threatened & Endangered Species Active Critical Habitat Report. The City of Redmond uses groundwater as a primary water source and maintains specific guidelines in order to protect groundwater quality. The site is located within Wellhead Protection Zone 1 where new construction of stormwater infiltration facilities is prohibited.

3.2 Topography

The existing site is currently undeveloped and contains a stormwater detention pond of roughly 0.08 acres, 1.16 acres of flat (0-5% slopes) pervious area, 1.16 acres of moderately sloped (5-10% slopes) pervious area, and 0.78 acres of steep (>15% slopes) pervious area. The highest elevation of 76' is located approximately 100' north of the existing stormwater pond. The bottom of the existing stormwater pond is the lowest elevation of 47.4'. General slope direction onsite is east to west towards 185th Ave NE. Slopes used to model predeveloped conditions were determined with a USGS Topography map circa 1950. See Technical Appendix: Exhibit 1 – Redmond Quadrangle (N4797.5-W12200/7.5).

3.3 Climate

The site is located in King County approximately 110 miles inland from the Pacific Ocean. Average annual temperatures range from 45°F to 61°F and average annual rainfall recorded in this area is 38 inches.

3.4 Site Geology

The underlying soil type onsite, is classified by the United States Department of Agriculture Soil Survey of King County, Washington, are identified in Table 3-1. See Technical Appendix: Hydrologic Soil Group - King County.

Table 3-1 Soil Characteristics

Soil Type	Hydrologic Group
Everett very gravelly sandy loam	A

3.5 Hydrology

3.5.1 Onsite Hydrology

The existing on-site conditions are predominately pervious. Stormwater drains west towards 185th Ave NE due to existing topography. There is an existing stormwater detention pond on the southern portion of the site which infiltrates stormwater runoff from an existing UPS parking lot located west of 185th Ave NE. Runoff from the existing parking lot is treated by a bio-infiltration swale prior to infiltration.

3.5.2 Offsite Hydrology

A stormwater swale runs north-south along the east side of 185th Ave NE, within a utility easement, which treats runoff from the existing sidewalk and roadway surface. Excess stormwater is conveyed by an 8-inch overflow pipe into the existing stormwater sewer. The stormwater sewer flows south along 185th Ave NE and then flows west along NE 76th St. Flow then continues along NE 76th St until it crosses US Highway 520 where it then discharges into a stormwater ditch that drains into Bear Creek.

3.6 Basin Areas

Basin areas for pre-developed conditions are shown in Table 3-2. The total property area used for this analysis is 2.65 acres out of the parcel's 3.27. The existing sidewalk and stormwater swale within the utility easement located on the east side of 185th Ave NE were not included in the analysis since they are part of a separate basin.

Table 3-2 Pre-Developed Basin Areas

Basin	Area (sf)	Area (ac)
Moderate Slope	57609	1.32
Steep Slope	57609	1.32
Total	115219	2.65

4 POST-DEVELOPED CONDITIONS

4.1 Hydrology

Drainage patterns of the subject property are not affected by offsite hydrology due to existing topography. Proposed site grading will preserve offsite drainage patterns and will not require the treatment, detention and conveyance of offsite runoff. No stormwater runoff generated by new impervious surfaces will be allowed to drain offsite. Runoff will be captured via catch basins, routed to detention pipe and then conveyed to a biofiltration

vault where runoff will be treated to required levels. Metered flow will be discharged into the existing stormwater sewer were it will eventually make its way to Bear Creek.

4.2 Basin Areas

The impervious and pervious surface areas for the post-developed conditions are shown in summary in Table 4-1. As mentioned above, the total property area used for this analysis is 2.65 acres. (See Technical Appendix: Post-Developed Basin Summary Delineation).

Table 4-1 Post-Developed Basin Delineation Summary

Basin	Impervious Area (sf)	Impervious Area (ac)
Flat Lawn	11546	0.265
Moderate Lawn	7509	0.172
Steep Lawn	6547	0.150
Moderate Parking	89803	2.062
Total	115404	2.649

5 HYDROLOGIC ANALYSIS DESIGN GUIDELINES

5.1 Design Guidelines

The site is located within jurisdiction of the City of Redmond. The analysis and design criteria used for stormwater management described in this section will follow Washington Department of Ecology's Stormwater Management Manual for Western Washington, amended in December 2014, and the City of Redmond's Clearing, Grading, and Stormwater Management Technical Notebook (Technical Notebook), amended February 2012.

5.2 Western Washington Hydrology Model

The detention system to accommodate stormwater runoff from the proposed site improvements was modeled and sized with the Western Washington Hydrology Model (WWHM). WWHM is a continuous model which calculates runoff and detention volumes continuously based on historical data from 1948 to 2009. Onsite soils were modeled as till Group C soils due to excessively drained conditions. According to the City of Redmond's Clearing, Grading, and Stormwater Technical Notebook, proposed projects within Wellhead Protection Zones (WPZ) 1 and 2 are allowed to be modeled as Group C soils for flow control. Stormwater infiltration is prohibited in WPZ 1 and 2 and onsite infiltration rates in these areas are usually so large that design and construction of a detention facility that preserves pre-developed conditions would be impractical.

5.3 System Capacities


Results from the WWHM (See Technical Appendix – WWHM2012 Project Report) indicate that the proposed subsurface detention facility must provide at least 0.896 acre-feet of storage in order to maintain post development discharge rates from 50% of the 2-year peak flow to the full 50-year peak flow at pre development levels. The flow control structure is to consist of a 54-inch diameter precast manhole with a flow control tee and riser. The riser shall be 5.89 feet tall and have a diameter of 18-inches. Orifice dimensions and locations are indicated in Figure 5-1 below.

Table 5-1 Flow Control Structure Geometry

Orifice Diameter (inches)	Height (feet)
1.03	0.0000
1.55	3.53
0.93	4.02

Detention capacity will be provided by three Contech Duromaxx 7-foot diameter, 320-feet long steel reinforced polyethylene pipes. Pipes are to have one foot of freeboard and a combined capacity of 0.92 acre-feet. A volume curve for the proposed detention facility is presented below. WWHM output data can be found in the Technical Appendix section at the end of this report.

Figure 5-1 Volume Curve for 84" Duromaxx



6 Water Quality

6.1 Water Quality Facility

Per Section I-2.5.6 of the Stormwater Management Manual for Western Washington, projects with pollution-generating hard surfaces in excess of 5,000 square feet require treatment of stormwater runoff. Three BioClean Modular Wetland Biofiltration systems are proposed to treat stormwater runoff from the new parking lot and are to be constructed downstream of the proposed detention vaults. The Biofiltration system must be sized to treat the stormwater runoff volume generated from a 6-month, 24-hour storm event. Design requirements for the proposed development are summarized in Figure 6-1 below. Design values were determined with the Western Washington Hydrology Model.

Table 6-1 Water Quality Design

Design Water Quality Flow and Volume Off-line facility target flow 0.0285 cfs

Stormwater runoff for the proposed parking lot will be treated with a 4' x 4' Bioclean MWS Linear Vault. The water quality treatment capacity of the MWS Linear should provide adequate stormwater treatment considering design parameters. All MWS Linear Vaults are off-line treatment facilities and require a minimum of 3.4-ft of operating head between inlet and outlet inverts. An internal bypass wier is built into the 4' x 4' MWS Linear in order to bypass flows exceeding treatment flow capacity. See Figure 6-2 for MWS Linear water quality capacity values.

Table 6-2 Water Quality Capacity

Water Quality Flow and Volume Capacity					
Treatment Flow Rate					
0.052 cfs					

7 Conveyance Analysis

They proposed stormwater piping network was analyzed using the Rational Method to size storm drain piping for adequate conveyance. The 2015 Washington Department of Transportation Hydraulics Manual (Hydraulics Manual) was referenced for the determination of Mean Recurrence Interval (MRI) Values, Runoff Coefficients, and Ground Cover Coefficients. MRI values for Seattle, Washington were used in calculating stormwater runoff flow since the Western Washington Hydrology Model uses rain data from Seattle to size detention facilities. According to Technical Notebook, conveyance systems upstream of detention facilities should be designed to convey the 50-year flow. MRI Values for Seattle were determined from Figure 2-5.4A in the Hydraulics Manual and are summarized in the Table 7-1 below.

Table 7-1 MRI Values

	50-Year			
m	7.88			
n	0.545			

Onsite soils exhibit infiltration rates greater than 50 inches per hour and landscape areas are unlikely to generate any appreciable stormwater runoff flow, and were neglected from the analysis. Flow regimes over the proposed parking lot will consist of sheet flow and gutter flow thus ground cover coefficients of 1,200 (paved) and 1,500 (gutter) were selected from Figure 2-5.3 in the Hydraulics Manual. A minimum time of concentration of 5-minutes was used for analysis since time of concentration calculations for sheet and gutter flow resulted in values smaller than 5-minutes. Runoff Coefficients are tabulated in Figure 2-5.2 of the Hydraulics Manual for the 10-year peak storm. According to the Hydraulics Manual, Runoff coefficients should be factored for use with higher intensity storms to compensate for soil saturation. However, as mentioned above, onsite soils exhibit high infiltration rates, so a Runoff Coefficient of 0.9 was chosen. Runoff Coefficients and Ground Cover Coefficients used for conveyance analysis are summarized below.

Rainfall intensity was calculated to be 3.28 inches per hour using equation 2-4 below from the Hydraulics Manual.

$$I = \frac{m}{(T_c)^n} \tag{2-4}$$

Where:

= rainfall intensity in inches per hour (millimeters per hour)

T_c = time of concentration in minutes

m & n = coefficients in dimensionless units (Figures 2-5.4A and 2-5.4B)

The proposed parking lot was split into sub-basins and the corresponding stormwater flows were calculated. See the Post-Developed Basin Delineation for Conveyance in the Technical Appendix. Table 7-3 provides a summary of flow rates generated by parking lot sub-basins.

Table 7-2 Stormwater Flow Values for Sub-Basins

Sub-Basin	Area (ac.)	Flow (cfs)
A	0.196	0.578
В	0.249	0.734
С	0.384	1.132
D	0.189	0.557
E	0.249	0.734
F	0.249	0.734
G	0.105	0.310
Н	0.314	0.926
I	0.131	0.386

Pipe sizes, lengths and slopes are also indicated in the Post-Developed Basin Dileneation for Conveyance. Table 7-4 contains Manning's Equation calculations for the proposed storm system.

Table 7-3 Stormwater Flow Values for Sub-Basins

		CONVEYA	NCE DATA (50-YE	R STORM	EVENT)			Cardn	0
		UPS R	edmond - F	Redmor	d, Washin	gton			<i>Gai ui i</i>	
	Location Conduit Conduit					onduit	Results			
	Sta	tion	Proper	ties				rtocano		
Sub Basin	From	То	Diameter	Slope	Design Capacity	Qmax/ Qdesign	Max Flow	Max Velocity	Max Flow Depth	y/d0
			ft	%	cfs		cfs	ft/s	ft	
С	CB - (134)	CB - (52)	0.67	2.15	1.77	0.65	1.14	5.40	0.39	0.59
C+B	CB - (52)	DETENTION	0.83	2.66	3.57	0.53	1.88	6.64	0.43	0.52
Α	CB - (53)	DETENTION	0.50	34.61	3.30	0.20	0.65	13.05	0.15	0.30
F	CB - (109)	CB - (106)	0.83	0.30	1.20	0.63	0.76	2.33	0.48	0.58
F+E	CB - (106)	DETENTION	1.00	0.30	1.95	0.76	1.48	2.73	0.65	0.65
D	CB - (136)	DETENTION	0.50	10.16	1.79	0.34	0.60	8.22	0.20	0.40
G	CB - (72)	DETENTION	0.67	0.30	0.66	0.47	0.31	1.86	0.32	0.49
I	CB - (95)	DETENTION	0.67	0.30	0.66	0.59	0.39	1.98	0.37	0.56
Н	CB - (34)	DETENTION	0.83	0.30	1.20	0.77	0.93	2.43	0.55	0.66
	DETENTION	WATER QUALITY	1.00	0.30	1.95	1.08	2.10	2.74	0.94	0.94
	WATER QUALITY	STORM SEWER	1.00	0.75	3.09	1.08	3.32	4.33	0.94	0.94

8 Qualitative Downstream Analysis

A qualitative downstream analysis was prepared using GIS data provided by the City of Redmond. Downstream analysis included review of stormwater infrastructure beginning from the intersection of 185th Ave NE and NE Union Hill Rd to the point where Bear Creek crosses Redmond Way, near the intersection of Redmond Way and NE 76th St.

Stormwater runoff from improvements to 185th Ave NE are conveyed through an existing bioretention swale which runs the entire western length of the subject property. An 8-inch underdrain pipe conveys overflows from the bioretention swale to a 12-inch pipe. The 12-inch pipe then crosses over to the west side 185th Ave NE and flows south towards NE 76th St. The figures below illustrate the pipe size, slope and length of the existing stormwater sewer.



12-inch pipe is indicated in blue in Figure 7-1. The pipe length runs for approximately 121 If and then transitions into 18-inch pipe for the remaining distance to NE 76th St. This section of the storm sewer drains catch basins on either side of 185th Ave NE.




Figure 7-2 depicts the existing stormwater sewer consisting of 18-inch pipe. It appears that some onsite stormwater facilities are draining into the public storm sewer in addition to catch basins in the roadway.





Figure 7-3 shows connection points to the 18-inch public storm sewer. Once again, drainage consists of roadway catch basins and a couple connections from private stormwater facilities.



The 18-inch pipe illustrated in Figure 7-4 transitions to a 24-inch pipe at the corner of 185th Ave NE and 76th St NE. This section of the stormwater sewer drains catch basins along 185th Ave NE.



The storm sewer continues westward along the north side of NE 76th St for approximately 235 If with 24-inch pipe. The 24-inch pipe then crosses over to the south side of NE 76th St and continues west for approximately 362 If. Drainage for this section of the stormwater sewer originates from private stormwater facilities and catch basins along NE 76th St.




Figure 7-6 depicts the transition to 30-inch pipe which begins near the eastern end of parcel 2212950013 and continues west on NE 76th St for 911 lf.




Figure 7-7 is a continuation of the stormwater sewer section consisting of 30-inch pipe. This section of storm sewer drains a catch basin at the intersection of NE 76th St and 178th PI NE in addition to drainage conveyed from 180th Ave NE.





Figure 7-8 depicts the 36-inch storm sewer running along the southwest side of 178th PI NE. The public storm sewer transitions from 30-inch pipe to 36-inch pipe at the intersection of NE 76th St and 178th PI NE and continues along the southwest end of 178th PI NE for 224 lf. Drainage in this section of public sewer consists of roadway runoff.



The public storm sewer transitions from 36-inch pipe to 48-inch pipe as indicated in Figure 7-9. Drainage from a few private stormwater facilities is conveyed into the public storm sewer in addition to runoff from NE 76th St.




Figure 7-10 shows the existing storm sewer consisting of 48-inch pipe. This section of existing storm sewer drains stormwater runoff originating from Fred Meyer, Kohl's and NE 76^{th} St.





Figure 7-11 is a continuation of the existing storm sewer consisting of 48-inch pipe. This section of existing storm sewer drains stormwater runoff originating from Kohl's and Univar USA.




Stormwater conveyed from the 48-inch pipe discharges into an existing stormwater ditch that drains into Bear Creek, just north of Redmond Way. The ditch length is approximately 470 lf and has an 8% slope, see Figure 7-12.

9 SUMMARY

The proposed stormwater management approach follows the *Clearing, Grading, and Stormwater Management Technical Notebook* issued by the City of Redmond in February 2012 and the *2012 Stormwater Management Manual for Western Washington* amended by the Washington Department of Ecology in December 2014.

As previously mentioned, stormwater runoff treatment for the proposed parking lot will be provided by three BioClean Modular Wetlands systems and the detention system will consist of Duromaxx pipe chambers. StormTrap vaults will be installed in the area of the existing stormwater infiltration pond with no change in the quantity of stormwater disposal. The functionality of the existing infiltration facility will essentially be unmodified since no changes in drainage patterns are proposed.

The proposed storm water management system meets the requirements of the City of Redmond and the Washington Department of Ecology for stormwater conveyance and treatment.



Technical Appendix

- > Hydrologic Soil Group King County
- > Pre-Developed Basin USGS Topography
- > Existing Conditions
- > Post-Developed Basin Delineation
- > Post-Developed Basin Delineation for Conveyance
- > Geotechnical Report
- > WWHM UPS Redmond Output Report

References


- 1. Stormwater Management Manual for Western Washington. issued in 2012, amended December 2014 State of Washington Department of Ecology
- 2. Clearing, Grading, and Stormwater Management Technical Notebook. issued in August 2010, amended February 2012 City of Redmond
- 3. Soil Survey of King County Area. National Resource Conservation Service
- 4. Hydraulics Manual. Issued in 2015 Washington State Department of Transporation



VRCS

Natural Resources Conservation Service A product of the National Cooperative Soil Survey, a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local participants

Custom Soil Resource Report for King County Area, Washington



Preface

Soil surveys contain information that affects land use planning in survey areas. They highlight soil limitations that affect various land uses and provide information about the properties of the soils in the survey areas. Soil surveys are designed for many different users, including farmers, ranchers, foresters, agronomists, urban planners, community officials, engineers, developers, builders, and home buyers. Also, conservationists, teachers, students, and specialists in recreation, waste disposal, and pollution control can use the surveys to help them understand, protect, or enhance the environment.

Various land use regulations of Federal, State, and local governments may impose special restrictions on land use or land treatment. Soil surveys identify soil properties that are used in making various land use or land treatment decisions. The information is intended to help the land users identify and reduce the effects of soil limitations on various land uses. The landowner or user is responsible for identifying and complying with existing laws and regulations.

Although soil survey information can be used for general farm, local, and wider area planning, onsite investigation is needed to supplement this information in some cases. Examples include soil quality assessments (http://www.nrcs.usda.gov/wps/portal/nrcs/main/soils/health/) and certain conservation and engineering applications. For more detailed information, contact your local USDA Service Center (https://offices.sc.egov.usda.gov/locator/app?agency=nrcs) or your NRCS State Soil Scientist (http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/contactus/?cid=nrcs142p2 053951).

Great differences in soil properties can occur within short distances. Some soils are seasonally wet or subject to flooding. Some are too unstable to be used as a foundation for buildings or roads. Clayey or wet soils are poorly suited to use as septic tank absorption fields. A high water table makes a soil poorly suited to basements or underground installations.

The National Cooperative Soil Survey is a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local agencies. The Natural Resources Conservation Service (NRCS) has leadership for the Federal part of the National Cooperative Soil Survey.

Information about soils is updated periodically. Updated information is available through the NRCS Web Soil Survey, the site for official soil survey information.

The U.S. Department of Agriculture (USDA) prohibits discrimination in all its programs and activities on the basis of race, color, national origin, age, disability, and where applicable, sex, marital status, familial status, parental status, religion, sexual orientation, genetic information, political beliefs, reprisal, or because all or a part of an individual's income is derived from any public assistance program. (Not all prohibited bases apply to all programs.) Persons with disabilities who require

alternative means for communication of program information (Braille, large print, audiotape, etc.) should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD). To file a complaint of discrimination, write to USDA, Director, Office of Civil Rights, 1400 Independence Avenue, S.W., Washington, D.C. 20250-9410 or call (800) 795-3272 (voice) or (202) 720-6382 (TDD). USDA is an equal opportunity provider and employer.

Contents

Preface	2
How Soil Surveys Are Made	
Soil Map	
Soil Map	9
Legend	
Map Unit Legend	11
Map Unit Descriptions	
King County Area, Washington	
EvB—Everett very gravelly sandy loam, 0 to 8 percent slopes	13
EvC—Everett very gravelly sandy loam, 8 to 15 percent slopes	14
EvD—Everett very gravelly sandy loam, 15 to 30 percent slopes	15
InA—Indianola loamy sand, 0 to 5 percent slopes	17
PITS—Pits	18
Sk—Seattle muck	19
Su—Sultan silt loam	20
References	22

How Soil Surveys Are Made

Soil surveys are made to provide information about the soils and miscellaneous areas in a specific area. They include a description of the soils and miscellaneous areas and their location on the landscape and tables that show soil properties and limitations affecting various uses. Soil scientists observed the steepness, length, and shape of the slopes; the general pattern of drainage; the kinds of crops and native plants; and the kinds of bedrock. They observed and described many soil profiles. A soil profile is the sequence of natural layers, or horizons, in a soil. The profile extends from the surface down into the unconsolidated material in which the soil formed or from the surface down to bedrock. The unconsolidated material is devoid of roots and other living organisms and has not been changed by other biological activity.

Currently, soils are mapped according to the boundaries of major land resource areas (MLRAs). MLRAs are geographically associated land resource units that share common characteristics related to physiography, geology, climate, water resources, soils, biological resources, and land uses (USDA, 2006). Soil survey areas typically consist of parts of one or more MLRA.

The soils and miscellaneous areas in a survey area occur in an orderly pattern that is related to the geology, landforms, relief, climate, and natural vegetation of the area. Each kind of soil and miscellaneous area is associated with a particular kind of landform or with a segment of the landform. By observing the soils and miscellaneous areas in the survey area and relating their position to specific segments of the landform, a soil scientist develops a concept, or model, of how they were formed. Thus, during mapping, this model enables the soil scientist to predict with a considerable degree of accuracy the kind of soil or miscellaneous area at a specific location on the landscape.

Commonly, individual soils on the landscape merge into one another as their characteristics gradually change. To construct an accurate soil map, however, soil scientists must determine the boundaries between the soils. They can observe only a limited number of soil profiles. Nevertheless, these observations, supplemented by an understanding of the soil-vegetation-landscape relationship, are sufficient to verify predictions of the kinds of soil in an area and to determine the boundaries.

Soil scientists recorded the characteristics of the soil profiles that they studied. They noted soil color, texture, size and shape of soil aggregates, kind and amount of rock fragments, distribution of plant roots, reaction, and other features that enable them to identify soils. After describing the soils in the survey area and determining their properties, the soil scientists assigned the soils to taxonomic classes (units). Taxonomic classes are concepts. Each taxonomic class has a set of soil characteristics with precisely defined limits. The classes are used as a basis for comparison to classify soils systematically. Soil taxonomy, the system of taxonomic classification used in the United States, is based mainly on the kind and character of soil properties and the arrangement of horizons within the profile. After the soil

Custom Soil Resource Report

scientists classified and named the soils in the survey area, they compared the individual soils with similar soils in the same taxonomic class in other areas so that they could confirm data and assemble additional data based on experience and research.

The objective of soil mapping is not to delineate pure map unit components; the objective is to separate the landscape into landforms or landform segments that have similar use and management requirements. Each map unit is defined by a unique combination of soil components and/or miscellaneous areas in predictable proportions. Some components may be highly contrasting to the other components of the map unit. The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The delineation of such landforms and landform segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, onsite investigation is needed to define and locate the soils and miscellaneous areas.

Soil scientists make many field observations in the process of producing a soil map. The frequency of observation is dependent upon several factors, including scale of mapping, intensity of mapping, design of map units, complexity of the landscape, and experience of the soil scientist. Observations are made to test and refine the soil-landscape model and predictions and to verify the classification of the soils at specific locations. Once the soil-landscape model is refined, a significantly smaller number of measurements of individual soil properties are made and recorded. These measurements may include field measurements, such as those for color, depth to bedrock, and texture, and laboratory measurements, such as those for content of sand, silt, clay, salt, and other components. Properties of each soil typically vary from one point to another across the landscape.

Observations for map unit components are aggregated to develop ranges of characteristics for the components. The aggregated values are presented. Direct measurements do not exist for every property presented for every map unit component. Values for some properties are estimated from combinations of other properties.

While a soil survey is in progress, samples of some of the soils in the area generally are collected for laboratory analyses and for engineering tests. Soil scientists interpret the data from these analyses and tests as well as the field-observed characteristics and the soil properties to determine the expected behavior of the soils under different uses. Interpretations for all of the soils are field tested through observation of the soils in different uses and under different levels of management. Some interpretations are modified to fit local conditions, and some new interpretations are developed to meet local needs. Data are assembled from other sources, such as research information, production records, and field experience of specialists. For example, data on crop yields under defined levels of management are assembled from farm records and from field or plot experiments on the same kinds of soil.

Predictions about soil behavior are based not only on soil properties but also on such variables as climate and biological activity. Soil conditions are predictable over long periods of time, but they are not predictable from year to year. For example, soil scientists can predict with a fairly high degree of accuracy that a given soil will have a high water table within certain depths in most years, but they cannot predict that a high water table will always be at a specific level in the soil on a specific date.


After soil scientists located and identified the significant natural bodies of soil in the survey area, they drew the boundaries of these bodies on aerial photographs and

Custom Soil Resource Report

identified each as a specific map unit. Aerial photographs show trees, buildings, fields, roads, and rivers, all of which help in locating boundaries accurately.

Soil Map

The soil map section includes the soil map for the defined area of interest, a list of soil map units on the map and extent of each map unit, and cartographic symbols displayed on the map. Also presented are various metadata about data used to produce the map, and a description of each soil map unit.



MAP LEGEND

Area of Interest (AOI)

Area of Interest (AOI)

Soils

Soil Map Unit Polygons

Soil Map Unit Lines

Soil Map Unit Points

Special Point Features

(o)

Blowout

Borrow Pit

Clay Spot

Closed Depression

Gravel Pit

Gravelly Spot

Landfill

Lava Flow Marsh or swamp

Mine or Quarry

Miscellaneous Water Perennial Water

Rock Outcrop

Saline Spot

Sandy Spot

Severely Eroded Spot

Sinkhole

Sodic Spot

Slide or Slip

Spoil Area



Stony Spot

00

Very Stony Spot

Ŷ

Wet Spot Other

Δ

Special Line Features

Water Features

Streams and Canals

Transportation

Rails

Interstate Highways

US Routes

Major Roads

00

Local Roads

Background

Aerial Photography

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:24.000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service Web Soil Survey URL:

Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: King County Area, Washington Survey Area Data: Version 12, Sep 8, 2016

Soil map units are labeled (as space allows) for map scales 1:50.000 or larger.

Date(s) aerial images were photographed: Aug 31, 2013—Oct 6, 2013

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Map Unit Legend

King County Area, Washington (WA633)					
Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI		
EvB	Everett very gravelly sandy loam, 0 to 8 percent slopes	28.1	37.2%		
EvC	Everett very gravelly sandy loam, 8 to 15 percent slopes	22.0	29.1%		
EvD	Everett very gravelly sandy loam, 15 to 30 percent slopes	8.7	11.5%		
InA	Indianola loamy sand, 0 to 5 percent slopes	3.5	4.7%		
PITS	Pits	8.4	11.1%		
Sk	Seattle muck	2.8	3.8%		
Su	Sultan silt loam	2.0	2.7%		
Totals for Area of Interest		75.5	100.0%		

Map Unit Descriptions

The map units delineated on the detailed soil maps in a soil survey represent the soils or miscellaneous areas in the survey area. The map unit descriptions, along with the maps, can be used to determine the composition and properties of a unit.

A map unit delineation on a soil map represents an area dominated by one or more major kinds of soil or miscellaneous areas. A map unit is identified and named according to the taxonomic classification of the dominant soils. Within a taxonomic class there are precisely defined limits for the properties of the soils. On the landscape, however, the soils are natural phenomena, and they have the characteristic variability of all natural phenomena. Thus, the range of some observed properties may extend beyond the limits defined for a taxonomic class. Areas of soils of a single taxonomic class rarely, if ever, can be mapped without including areas of other taxonomic classes. Consequently, every map unit is made up of the soils or miscellaneous areas for which it is named and some minor components that belong to taxonomic classes other than those of the major soils.

Most minor soils have properties similar to those of the dominant soil or soils in the map unit, and thus they do not affect use and management. These are called noncontrasting, or similar, components. They may or may not be mentioned in a particular map unit description. Other minor components, however, have properties and behavioral characteristics divergent enough to affect use or to require different management. These are called contrasting, or dissimilar, components. They generally are in small areas and could not be mapped separately because of the scale used. Some small areas of strongly contrasting soils or miscellaneous areas are identified by a special symbol on the maps. If included in the database for a given area, the contrasting minor components are identified in the map unit descriptions along with some characteristics of each. A few areas of minor components may not have been observed, and consequently they are not

Custom Soil Resource Report

mentioned in the descriptions, especially where the pattern was so complex that it was impractical to make enough observations to identify all the soils and miscellaneous areas on the landscape.

The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The objective of mapping is not to delineate pure taxonomic classes but rather to separate the landscape into landforms or landform segments that have similar use and management requirements. The delineation of such segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, however, onsite investigation is needed to define and locate the soils and miscellaneous areas.

An identifying symbol precedes the map unit name in the map unit descriptions. Each description includes general facts about the unit and gives important soil properties and qualities.

Soils that have profiles that are almost alike make up a *soil series*. Except for differences in texture of the surface layer, all the soils of a series have major horizons that are similar in composition, thickness, and arrangement.

Soils of one series can differ in texture of the surface layer, slope, stoniness, salinity, degree of erosion, and other characteristics that affect their use. On the basis of such differences, a soil series is divided into *soil phases*. Most of the areas shown on the detailed soil maps are phases of soil series. The name of a soil phase commonly indicates a feature that affects use or management. For example, Alpha silt loam, 0 to 2 percent slopes, is a phase of the Alpha series.

Some map units are made up of two or more major soils or miscellaneous areas. These map units are complexes, associations, or undifferentiated groups.

A *complex* consists of two or more soils or miscellaneous areas in such an intricate pattern or in such small areas that they cannot be shown separately on the maps. The pattern and proportion of the soils or miscellaneous areas are somewhat similar in all areas. Alpha-Beta complex, 0 to 6 percent slopes, is an example.

An association is made up of two or more geographically associated soils or miscellaneous areas that are shown as one unit on the maps. Because of present or anticipated uses of the map units in the survey area, it was not considered practical or necessary to map the soils or miscellaneous areas separately. The pattern and relative proportion of the soils or miscellaneous areas are somewhat similar. Alpha-Beta association, 0 to 2 percent slopes, is an example.

An *undifferentiated group* is made up of two or more soils or miscellaneous areas that could be mapped individually but are mapped as one unit because similar interpretations can be made for use and management. The pattern and proportion of the soils or miscellaneous areas in a mapped area are not uniform. An area can be made up of only one of the major soils or miscellaneous areas, or it can be made up of all of them. Alpha and Beta soils, 0 to 2 percent slopes, is an example.

Some surveys include *miscellaneous areas*. Such areas have little or no soil material and support little or no vegetation. Rock outcrop is an example.

King County Area, Washington

EvB—Everett very gravelly sandy loam, 0 to 8 percent slopes

Map Unit Setting

National map unit symbol: 2t629

Elevation: 30 to 900 feet

Mean annual precipitation: 35 to 91 inches
Mean annual air temperature: 48 to 52 degrees F

Frost-free period: 180 to 240 days

Farmland classification: Farmland of statewide importance

Map Unit Composition

Everett and similar soils: 80 percent Minor components: 20 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Everett

Setting

Landform: Eskers, moraines, kames

Landform position (two-dimensional): Summit, shoulder Landform position (three-dimensional): Crest, interfluve

Down-slope shape: Convex Across-slope shape: Convex

Parent material: Sandy and gravelly glacial outwash

Typical profile

Oi - 0 to 1 inches: slightly decomposed plant material

A - 1 to 3 inches: very gravelly sandy loam
Bw - 3 to 24 inches: very gravelly sandy loam
C1 - 24 to 35 inches: very gravelly loamy sand
C2 - 35 to 60 inches: extremely cobbly coarse sand

Properties and qualities

Slope: 0 to 8 percent

Depth to restrictive feature: More than 80 inches Natural drainage class: Somewhat excessively drained

Capacity of the most limiting layer to transmit water (Ksat): High (1.98 to 5.95

in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None Frequency of ponding: None

Available water storage in profile: Low (about 3.2 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 4s

Hydrologic Soil Group: A

Other vegetative classification: Droughty Soils (G002XN402WA), Droughty Soils

(G002XF403WA), Droughty Soils (G002XS401WA)

Hydric soil rating: No

Minor Components

Alderwood

Percent of map unit: 10 percent

Landform: Ridges, hills

Landform position (two-dimensional): Summit Landform position (three-dimensional): Crest, talf

Down-slope shape: Linear, convex Across-slope shape: Convex

Hydric soil rating: No

Indianola

Percent of map unit: 10 percent Landform: Eskers, kames, terraces

Landform position (three-dimensional): Tread

Down-slope shape: Linear Across-slope shape: Linear Hydric soil rating: No

EvC—Everett very gravelly sandy loam, 8 to 15 percent slopes

Map Unit Setting

National map unit symbol: 2t62b

Elevation: 30 to 900 feet

Mean annual precipitation: 35 to 91 inches
Mean annual air temperature: 48 to 52 degrees F

Frost-free period: 180 to 240 days

Farmland classification: Farmland of statewide importance

Map Unit Composition

Everett and similar soils: 80 percent Minor components: 20 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Everett

Setting

Landform: Kames, eskers, moraines

Landform position (two-dimensional): Shoulder, footslope Landform position (three-dimensional): Crest, base slope

Down-slope shape: Convex Across-slope shape: Convex

Parent material: Sandy and gravelly glacial outwash

Typical profile

Oi - 0 to 1 inches: slightly decomposed plant material

A - 1 to 3 inches: very gravelly sandy loam
Bw - 3 to 24 inches: very gravelly sandy loam
C1 - 24 to 35 inches: very gravelly loamy sand
C2 - 35 to 60 inches: extremely cobbly coarse sand

Custom Soil Resource Report

Properties and qualities

Slope: 8 to 15 percent

Depth to restrictive feature: More than 80 inches Natural drainage class: Somewhat excessively drained

Capacity of the most limiting layer to transmit water (Ksat): High (1.98 to 5.95

in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None Frequency of ponding: None

Available water storage in profile: Low (about 3.2 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 4s

Hydrologic Soil Group: A

Other vegetative classification: Droughty Soils (G002XN402WA), Droughty Soils

(G002XS401WA), Droughty Soils (G002XF403WA)

Hydric soil rating: No

Minor Components

Alderwood

Percent of map unit: 10 percent

Landform: Ridges, hills

Landform position (two-dimensional): Shoulder

Landform position (three-dimensional): Nose slope, talf

Down-slope shape: Linear, convex Across-slope shape: Convex

Hydric soil rating: No

Indianola

Percent of map unit: 10 percent Landform: Eskers, kames, terraces

Landform position (three-dimensional): Riser

Down-slope shape: Linear Across-slope shape: Linear Hydric soil rating: No

EvD—Everett very gravelly sandy loam, 15 to 30 percent slopes

Map Unit Setting

National map unit symbol: 2t62c

Elevation: 30 to 900 feet

Mean annual precipitation: 35 to 91 inches Mean annual air temperature: 48 to 52 degrees F

Frost-free period: 180 to 240 days

Farmland classification: Farmland of statewide importance

Map Unit Composition

Everett and similar soils: 80 percent

Custom Soil Resource Report

Minor components: 20 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Everett

Setting

Landform: Kames, eskers, moraines

Landform position (two-dimensional): Backslope Landform position (three-dimensional): Side slope

Down-slope shape: Convex Across-slope shape: Convex

Parent material: Sandy and gravelly glacial outwash

Typical profile

Oi - 0 to 1 inches: slightly decomposed plant material

A - 1 to 3 inches: very gravelly sandy loam
Bw - 3 to 24 inches: very gravelly sandy loam
C1 - 24 to 35 inches: very gravelly loamy sand
C2 - 35 to 60 inches: extremely cobbly coarse sand

Properties and qualities

Slope: 15 to 30 percent

Depth to restrictive feature: More than 80 inches Natural drainage class: Somewhat excessively drained

Capacity of the most limiting layer to transmit water (Ksat): High (1.98 to 5.95

in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None Frequency of ponding: None

Available water storage in profile: Low (about 3.2 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 4e

Hydrologic Soil Group: A

Other vegetative classification: Droughty Soils (G002XN402WA), Droughty Soils

(G002XS401WA) Hydric soil rating: No

Minor Components

Alderwood

Percent of map unit: 10 percent

Landform: Ridges, hills

Landform position (two-dimensional): Backslope

Landform position (three-dimensional): Side slope, nose slope, talf

Down-slope shape: Linear, convex Across-slope shape: Convex

Hydric soil rating: No

Indianola

Percent of map unit: 10 percent Landform: Eskers, kames, terraces

Landform position (two-dimensional): Backslope Landform position (three-dimensional): Side slope

Down-slope shape: Linear Across-slope shape: Linear

Hydric soil rating: No

InA—Indianola loamy sand, 0 to 5 percent slopes

Map Unit Setting

National map unit symbol: 2t62k

Elevation: 0 to 980 feet

Mean annual precipitation: 30 to 81 inches Mean annual air temperature: 48 to 50 degrees F

Frost-free period: 170 to 210 days

Farmland classification: Prime farmland if irrigated

Map Unit Composition

Indianola and similar soils: 85 percent Minor components: 15 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Indianola

Setting

Landform: Eskers, kames, terraces

Landform position (three-dimensional): Tread

Down-slope shape: Linear Across-slope shape: Linear

Parent material: Sandy glacial outwash

Typical profile

Oi - 0 to 1 inches: slightly decomposed plant material

A - 1 to 6 inches: loamy sand Bw1 - 6 to 17 inches: loamy sand Bw2 - 17 to 27 inches: sand BC - 27 to 37 inches: sand C - 37 to 60 inches: sand

Properties and qualities

Slope: 0 to 5 percent

Depth to restrictive feature: More than 80 inches Natural drainage class: Somewhat excessively drained

Capacity of the most limiting layer to transmit water (Ksat): High to very high (5.95

to 99.90 in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None Frequency of ponding: None

Available water storage in profile: Low (about 3.9 inches)

Interpretive groups

Land capability classification (irrigated): 4s Land capability classification (nonirrigated): 4s

Hydrologic Soil Group: A

Custom Soil Resource Report

Other vegetative classification: Droughty Soils (G002XV402WA), Droughty Soils

(G002XF403WA), Droughty Soils (G002XS401WA), Droughty Soils

(G002XN402WA) *Hydric soil rating:* No

Minor Components

Alderwood

Percent of map unit: 8 percent

Landform: Ridges, hills

Landform position (two-dimensional): Summit Landform position (three-dimensional): Crest, talf

Down-slope shape: Linear, convex Across-slope shape: Convex

Hydric soil rating: No

Everett

Percent of map unit: 5 percent Landform: Kames, eskers, moraines

Landform position (two-dimensional): Summit, shoulder Landform position (three-dimensional): Crest, interfluve

Down-slope shape: Convex Across-slope shape: Convex

Hydric soil rating: No

Norma

Percent of map unit: 2 percent

Landform: Depressions, drainageways Landform position (three-dimensional): Dip

Down-slope shape: Concave, linear Across-slope shape: Concave

Hydric soil rating: Yes

PITS—Pits

Map Unit Composition

Pits: 100 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Pits

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 8

Hydric soil rating: No

Sk—Seattle muck

Map Unit Setting

National map unit symbol: 1hmv4

Elevation: 0 to 1,000 feet

Mean annual precipitation: 25 to 50 inches Mean annual air temperature: 48 to 52 degrees F

Frost-free period: 150 to 250 days

Farmland classification: Prime farmland if drained

Map Unit Composition

Seattle and similar soils: 75 percent *Minor components*: 25 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Seattle

Setting

Landform: Depressions

Parent material: Grassy organic material

Typical profile

H1 - 0 to 11 inches: muck

H2 - 11 to 60 inches: stratified mucky peat to muck

Properties and qualities

Slope: 0 to 1 percent

Depth to restrictive feature: More than 80 inches Natural drainage class: Very poorly drained

Capacity of the most limiting layer to transmit water (Ksat): Moderately high to

high (0.57 to 1.98 in/hr)

Depth to water table: About 0 inches

Frequency of flooding: None Frequency of ponding: Frequent

Available water storage in profile: Very high (about 23.5 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 5w

Hydrologic Soil Group: B/D

Other vegetative classification: Wet Soils (G002XN102WA)

Hydric soil rating: Yes

Minor Components

Tukwila

Percent of map unit: 10 percent

Landform: Depressions Hydric soil rating: Yes

Shalcar

Percent of map unit: 10 percent

Landform: Depressions

Custom Soil Resource Report

Hydric soil rating: Yes

Bellingham

Percent of map unit: 3 percent Landform: Depressions Hydric soil rating: Yes

Norma

Percent of map unit: 2 percent Landform: Depressions Hydric soil rating: Yes

Su-Sultan silt loam

Map Unit Setting

National map unit symbol: 1hmv9

Elevation: 0 to 150 feet

Mean annual precipitation: 35 to 55 inches

Mean annual air temperature: 48 to 50 degrees F

Frost-free period: 150 to 200 days

Farmland classification: All areas are prime farmland

Map Unit Composition

Sultan and similar soils: 70 percent Minor components: 30 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Sultan

Setting

Landform: Flood plains
Parent material: Alluvium

Typical profile

H1 - 0 to 9 inches: ashy silt loam
H2 - 9 to 48 inches: silty clay loam

H3 - 48 to 60 inches: stratified sand to silt loam

Properties and qualities

Slope: 0 to 2 percent

Depth to restrictive feature: More than 80 inches Natural drainage class: Moderately well drained

Capacity of the most limiting layer to transmit water (Ksat): Moderately high to

high (0.57 to 1.98 in/hr)

Depth to water table: About 24 to 36 inches

Frequency of flooding: Occasional Frequency of ponding: None

Available water storage in profile: High (about 10.9 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 3w

Custom Soil Resource Report

Hydrologic Soil Group: C

Other vegetative classification: Seasonally Wet Soils (G002XN202WA)

Hydric soil rating: No

Minor Components

Puget

Percent of map unit: 10 percent

Landform: Flood plains Hydric soil rating: Yes

Sammamish

Percent of map unit: 10 percent

Landform: Flood plains
Hydric soil rating: Yes

Oridia

Percent of map unit: 10 percent

Landform: Flood plains
Hydric soil rating: Yes

References

American Association of State Highway and Transportation Officials (AASHTO). 2004. Standard specifications for transportation materials and methods of sampling and testing. 24th edition.

American Society for Testing and Materials (ASTM). 2005. Standard classification of soils for engineering purposes. ASTM Standard D2487-00.

Cowardin, L.M., V. Carter, F.C. Golet, and E.T. LaRoe. 1979. Classification of wetlands and deep-water habitats of the United States. U.S. Fish and Wildlife Service FWS/OBS-79/31.

Federal Register. July 13, 1994. Changes in hydric soils of the United States.

Federal Register. September 18, 2002. Hydric soils of the United States.

Hurt, G.W., and L.M. Vasilas, editors. Version 6.0, 2006. Field indicators of hydric soils in the United States.

National Research Council. 1995. Wetlands: Characteristics and boundaries.

Soil Survey Division Staff. 1993. Soil survey manual. Soil Conservation Service. U.S. Department of Agriculture Handbook 18. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_054262

Soil Survey Staff. 1999. Soil taxonomy: A basic system of soil classification for making and interpreting soil surveys. 2nd edition. Natural Resources Conservation Service, U.S. Department of Agriculture Handbook 436. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2 053577

Soil Survey Staff. 2010. Keys to soil taxonomy. 11th edition. U.S. Department of Agriculture, Natural Resources Conservation Service. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2 053580

Tiner, R.W., Jr. 1985. Wetlands of Delaware. U.S. Fish and Wildlife Service and Delaware Department of Natural Resources and Environmental Control, Wetlands Section.

United States Army Corps of Engineers, Environmental Laboratory. 1987. Corps of Engineers wetlands delineation manual. Waterways Experiment Station Technical Report Y-87-1.

United States Department of Agriculture, Natural Resources Conservation Service. National forestry manual. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/home/?cid=nrcs142p2 053374


United States Department of Agriculture, Natural Resources Conservation Service. National range and pasture handbook. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/landuse/rangepasture/?cid=stelprdb1043084


Custom Soil Resource Report

United States Department of Agriculture, Natural Resources Conservation Service. National soil survey handbook, title 430-VI. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/scientists/?cid=nrcs142p2_054242

United States Department of Agriculture, Natural Resources Conservation Service. 2006. Land resource regions and major land resource areas of the United States, the Caribbean, and the Pacific Basin. U.S. Department of Agriculture Handbook 296. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053624

United States Department of Agriculture, Soil Conservation Service. 1961. Land capability classification. U.S. Department of Agriculture Handbook 210. http://www.nrcs.usda.gov/Internet/FSE_DOCUMENTS/nrcs142p2_052290.pdf





POST-DEVELOPED BASIN DELINEATION UPS PARCEL DISTRIBUTION FACILITY

UNITED PARCEL SERVICE REDMOND, WA


11/18/2016 21612460

> DATE: ΒΥ.

PROJECT NO.

LAG

SHEET NO.



DATE: BY:



GEOTECHNICAL ENGINEERING REPORT

Proposed New Parking Lot 18001 NE Union Hill Road Redmond, WA

PSI PROJECT NO.07121335

February 25, 2016

Prepared for:

United Parcel Service 6177 N Basin Avenue Portland, Oregon 97217

Prepared by:

Professional Service Industries, Inc. 20508 - 56th Ave W, Suite A Lynnwood, WA 98036



February 25, 2016

United Parcel Service 6177 N Basin Avenue Portland, Oregon, 97217

Attention:

Buddy Dobberthein,

Project Engineer

odobberthein@ups.com

(360) 901-8236

Subject:

Geotechnical Investigation Proposed New Parking Lot 18001 NE Union Hill Road Redmond, Washington PSI Project # 07121335

Dear Mr. Dobberthein,

Professional Service Industries, Inc. (PSI) is pleased to submit a report of our geotechnical investigation for a new parking lot for United Parcels Service facility, in Redmond, Washington. This report summarizes the work accomplished and provides our recommendations for design and construction of the proposed project. PSI performed the requested geotechnical investigation services in general accordance with the design services agreement, dated January 21, 2016.

Based on the results of our field investigation, laboratory testing and engineering analysis, the proposed site is suitable for the construction of the proposed improvements from a geotechnical standpoint, provided the recommendations of this report are followed. Recommendations regarding the geotechnical aspects of project design and construction are presented in the attached report.

PSI appreciates the opportunity to contribute our services and looks forward to working with you during design and construction of this project. Please contact the undersigned directly if you have questions pertaining to this project.

Respectfully Submitted,

PROFESSIONAL SERVICE INDUSTRIES, INC.

Michael S. Place P.E. Principal Consultant

Email: michael.place@psiusa.com

Phone: (425-409-2505)

Stephen R. Bryant, PE Senior Vice President

Professional Service Industries, Inc. Engineering • Consulting • Testing February 25, 2016 Page 1

1. PROJECT DESCRIPTION

PSI understands that United Parcel Service (UPS) is planning on constructing a parking lot on the southeast corner of the intersection of NE Union Hill road and 185th Avenue NE, in Redmond, Washington. As part of the new parking lot, a shallow infiltration system will be installed to handle the stormwater runoff from the new asphalt surfaces.

2. SITE DESCRIPTION

2.1. General

The site is located at 18001 NE Union Hill Road in Redmond, Washington. The site is bound by 185th Avenue NE to the west NE Union Hill Road to the north and commercial properties to the south and east. The site is currently covered by minor grasses and patches of exposed sand and gravel soil. Additionally, the site appears to have been excavated 10 feet in places during the expansion of 185th Avenue NE in 2011. This is based on observations made during our field investigation and on historical aerial imagery on Google Earth.

2.2. Topography

Based on our field investigation the site slopes gently down at approximately at 6 horizontal to 1 vertical from east to west towards 185th Avenue NE. Based on the nearby street and adjoining property elevations shown on Google Earth the site elevations appear to vary from 65 to 75 feet above mean sea level.

2.3. Geology

Based upon a review of Washington State Department of Natural Resources Interactive Maps (Reference 1) and the results of our field investigation the site is underlain by outwash deposits. Outwash typically consists of silts sands and gravels deposited by glacial meltwater. The nearest fault zone to the site is the Southern Whidbey Island Fault Zone approximately 4.5 miles north of the site. The Southern Whidbey Island Fault Zone trends northwest to southeast, is of unspecified age and has had no measurable movement recorded since initial monitoring of the fault (Reference 2).

2.4. Subsurface conditions

Subsurface materials and conditions were investigated with three soil borings and five infiltration test borings using hollow stem auger drilling techniques. Soil borings were designated B-1 through B-3 and Infiltration test borings were designated I-1 through I-5 were drilled on February 12, 2016. The three soil borings were drilled to depths of approximately 16½ feet below existing site grades (bgs) and the five infiltration test borings were drilled to approximately 3 feet bgs. The approximate locations of the soil and infiltration test borings are shown on Figure 2.

In general, the soils under the proposed parking lot areas generally consist of medium dense to dense poorly graded sand with silt and gravel and poorly graded gravel with sand. A detailed description of our field investigation and our boring logs are available in Appendix A. A description of the laboratory testing program along with sample test results are available in Appendix B. The terms used to describe material

encountered in the boring are defined in the General Notes, in Appendix A. A summary of the soils as they were encountered from the ground surface is provided below.

OUTWASH: The outwash soil consisted of brown poorly graded sand with gravel and poorly graded gravel with sand. Standard Penetration Test N-Values in the fill ranged from 11 to 55 blows per foot indicating the relative densities of medium dense to very dense soil. The existing moisture content of the fill ranges from 2 to 14 percent.

2.5. Groundwater

Groundwater was not observed onsite during our field investigation or after 24 hour readings obtained from the three soil boring locations. Based on observed groundwater noted in listed wells with the Department of Ecology (Reference 3), groundwater in this area was observed near an elevation of approximately 35 feet above mean sea level. Since site elevation appear to range from 65 to 75 feet above mean sea level, we anticipate that groundwater at the site is approximately 30 feet below the lowest elevation on the property. PSI anticipates that the groundwater table will fluctuate seasonally and in response to significant precipitation events and perched groundwater be present at shallower depths certain times of year.

2.6. Field Infiltration Testing

PSI performed five infiltration tests this investigation. These infiltration tests were conducted at the approximate depths of 3 feet bgs. Infiltration tests were conducted in shallow borings above the groundwater table in 4-inch inside diameter PVC pipes set in contact with the relatively undisturbed soil at the base of the boring. Native soils were then backfilled around the pipes. In the base of the pipe approximately 1-inch of washed pea gravel was placed in the base of the PVC pipe to prevent siltation during testing. In each boring PSI attempted to presoak the soils but the six-inch water column PSI attempted to maintain exited the infiltration test locations in less than 5 minutes and some drained out in a matter of seconds. After each attempted presoak PSI performed infiltration testing by adding a six-inch column of water into the boring and measuring the time required to drain the water out the base of the pipe. Infiltration tests were completed at least two times in each location. Percolation tests conducted in infiltration borings I-1 and I-2 were conducted in poorly-graded sand with gravel soils at their bases. Infiltration tests conducted in infiltration borings I-3, I-4 and I-5 pockets of clean gravel were observed in the base of the borings where infiltration testing was conducted. The Infiltration rates ranged from approximately 50 to over 100 inches per hour. The infiltration rates listed in this report are measured field infiltration rates and do not have a factor of safety applied to them. Infiltration rates are indicative of the soils at the specific location, depth and time in which they were conducted. Variations of any of these factor may alter the observed infiltration rates. Infiltration rates measured during our field investigation are shown in Table 1 below.

Table 1: Summary of Infiltration Rates

Infiltration ID	ion ID Infiltration Rate (in./hr)		Longitude
I-1	50	47.67506	-122.09340
I-2	55	47.67587	-122.09342
I-3	>100	47.67600	-122.09342
I-4	>100	47.67652	-122.09287
I-5	>100	47.67575	-122.09304

3. CONCLUSIONS AND RECOMMENDATIONS

3.1. General

Subsurface explorations for this investigation indicate that the near surface soil on the site consist of medium dense poorly graded sand with silt and gravel. PSI believe the site is suitable for the specified improvements provided the recommendations stated in this report are followed.

3.2. Site Preparation

We anticipate that clearing and grubbing go the site will disturb approximately 3 to 4 inches of surface soils across the site. PSI further assumes that minor cuts and fills (less than 2 feet thick) will be required to regrade the site for the proposed parking lot.

3.3. Structural Fill

Fill placed beneath sidewalk, and pavement areas should be placed as compacted structural fill. We recommend that structural fill extends at least 2 feet beyond pavement limits where nearby structures do not restrict fill placement. On-site soils, outside of organic materials (such as topsoil) or other deleterious materials can be reused for backfill purposes, provided the material can obtain moisture contents that will allow it to meet compaction requirements. Imported material, if required, should be approved by the geotechnical engineer. Compacted fill should be placed in lifts of 12-inches (loose) or less by heavy compactors such as large vibratory rollers and hoe-packs and lifts of 6-inch (loose) or less for smaller compactors such as small plate compactors and jumping jacks. These soil should be moisture-conditioned to within 3 percent of the optimum moisture content, and compacted to a density of 95% of the maximum dry density as determined by ASTM D 1557.

The condition of the subgrade should be evaluated by a PSI representative before fill placement or construction begins. Fill compaction should be evaluated by in-place density tests performed during fill placement so that the adequacy of soil compaction efforts may be evaluated as earthwork progresses.

3.4. Utility Trench Excavations and Backfill

Excavations should be made in accordance with applicable Federal and State Occupational Safety and Health Administration regulations. Utility trenches in the near surface sand soils at the site will need to be slopes or shored from the ground surface due to the potential for caving. Actual inclinations will ultimately depend on the soil conditions encountered during earthwork. While we may provide certain approaches for trench excavations, the contractor should be responsible for selecting the excavation technique, monitoring the trench excavations for safety, and providing shoring, as required, to protect personnel and adjacent improvements. The information provided below is for use by the owner and engineer and should not be interpreted to mean that PSI is assuming responsibility for the contractor's actions or site safety. The soils PSI encountered within the upper 26 feet should be classified as Type C soil according to the most recent OSHA regulations. In our opinion, excavations should be safely sloped or shored. The contractor should be aware that excavation and shoring should conform to the requirements specified in the applicable local, state, and federal safety regulations, such as OSHA Health and Safety Standards for

Proposed Parking Lot of UPS Redmond Facility 18001 NE Union Hill Road, Redmond, WA PSI Project No.07121335 Professional Service Industries, Inc. Engineering • Consulting • Testing February 25, 2016 Page 4

Excavations, 29 CFR Part 1926, or successor regulations. We understand that such regulations are being strictly enforced, and if not followed, the contractor may be liable for substantial penalties.

Excavation and construction operations may expose the on-site soils to inclement weather conditions. The stability of exposed soils may deteriorate due to a change in moisture content or the action of heavy or repeated construction traffic. Accordingly, foundation and pavement area excavations should be protected from the elements and from the action of repetitive or heavy construction loadings.

Utilities trenches within the pavement, and sidewalk areas should be backfilled with granular structural fill such as sand, sand and gravel, crushed rock, or recycled concrete of up to 2 inches maximum size with less than 5 percent passing the No. 200 sieve (washed analysis). Granular backfill should be placed in lifts and compacted to 95 percent of the maximum dry density as determined by ASTM D 1557.

3.5. Pavement

We have made our design recommendations for new pavement sections assuming subgrade will be similar to the near-surface soils described in the boring logs. If the site soil conditions are different than those described in this report, we should be contacted so that we may confirm or modify the recommended pavement sections.

The soil type selected for the design subgrade consists of disturbed silty sand with gravel compacted to the requirements for structural fill outlined above. Based on our review of site soil conditions and the results of the California bearing ratio (CBR) testing, PSI has utilized a CBR value of 30 percent for our designs. This which is based on approximately 95% compaction.

The pavement section is dependent on the supporting capability of the subgrade soils and the traffic conditions to which it will be subjected. This parking lot is anticipated to cater small personal vehicles with only minor periods of time where heavier vehicles such as fire truck and bussed will enter the site. It should be recognized that standard pavement design methods are intended for through streets where accelerations are relatively low (i.e. velocities are relatively constant). Starting, stopping, and turning involve high accelerations. In these situations, the average daily traffic volume alone is insufficient to characterize the pavement loading. The Washington State Department of Transportation (WSDOT) Design Manual provides some guidance for designing pavement sections subjected to these higher accelerations.

As requested in the "Proposal Bid Package for Soil/Materials Engineering and Testing Services" provided by UPS for the Redmond Site, Dated December 16, 2015, PSI has prepared pavement design sections for 10-year and 20-year pavement section with overlay recommendation to make a 10-year pavement section into a 20-year pavement section, for Asphaltic Concrete (AC) with Crushed Rock Base (CRB), full depth AC, and Portland Cement Concrete (PCC) with CRB. PSI's designed pavement sections are listed in Table 2 Below.

Table 2: Pavement Design Sections						
_		Layer Thicknesses				
Pavement Life	ESAL's Used in Design	Type of Pavement	(In	icknesses ches) CRB 4 - 4 - - - - 4		
		AC and CRB 2 4				
		AC and CRB	2	4		
10-year	39500	Full Depth AC	3.5	-		
		Concrete	4	4		
2 1		AC and CRB	+1	-		
Overlay to Make 10 year a 20 year	87500	Full Depth AC	+1	-		
year a 20 year		Concrete	-			
		AC and CRB	2.5	4		
20-year	87500	Full Depth AC	4	- - -		
		Concrete	4	4		

Paving materials used should conform to the specifications. We recommend that aggregate for AC should meet the Class ½-inch grading requirements specified in Section 9-03.8(6), aggregate for CRB should conform to Section 9-03.9(3) Top Course of Crushed Surfacing.

Long-term pavement performance will depend on surface drainage. A poorly-drained pavement section will be subject to premature failure because of surface water infiltrating into the subgrade soils and reducing their supporting capability. If practical, we recommend new pavements be placed with surface drainage gradients of at least two percent for better long-term performance. Some longitudinal and transverse cracking of the pavement surface should be expected over time. Regular maintenance should be planned to seal cracks when they occur.

New pavement sections must be installed over firm subgrade. This means that the top 12 inches of subgrade should be free of organics and other debris and compacted in conformance with our recommendations in section 3.3 (Structural Fill). Paving should be performed as soon as practical after subgrade preparations are completed. Pavement subgrade surfaces should be proof-rolled and recompacted a second time with a heavy roller or equivalent immediately prior to constructing the pavement section if the prepared subgrade has been left unprotected for more than a few days or if it appears to have been disturbed from climatic conditions, excessive traffic, or other causes. We recommend that proof rolling be observed by a representative of the geotechnical engineer.

3.6. Drainage

We recommend pavement surfaces and open space areas be sloped such that surface water runoff is collected and routed to suitable discharge points. PSI recommends that any infiltration system used on this site be placed near the depth of the infiltration test performed for this investigation.

Our infiltration testing measured infiltration rates ranging from 50 to over 100 inches per hour. In our experience infiltration systems are not typically designed with rates exceeding 20 inches per hour, and as a

Professional Service Industries, Inc. Engineering • Consulting • Testing February 25, 2016 Page 6

result we would recommend that the infiltration system be designed utilizing an infiltration rate of 20 inches per hour. This will allow for a factor of safety of at least 2.5 in the areas tested, but may not fully account of siltation of the designed infiltration system over time.

4. DESIGN REVIEW AND CONSTRUCTION MONITORING

We welcome the opportunity to review and discuss construction plans and specifications as they are being developed. We are of the opinion that to observe compliance with the design concepts, specifications, and recommendations, construction operations dealing with earthwork and pavement installation should be observed by a qualified geotechnical engineer. We would be pleased to provide these services to you.

5. REPORT LIMITATIONS

The recommendations submitted in this report are based on the subsurface information obtained by PSI and design details furnished by representatives of the client, United Parcels Service, for the proposed improvements at 18001 East Union Hill Road in Redmond, Washington. If there are any revisions to the plans for this project, or if deviations from the subsurface conditions noted in this report are encountered during construction, PSI should be notified immediately to determine if changes in the foundation and/or pavement recommendations are required. If PSI is not retained to review these changes, PSI will not be responsible for the impact of those conditions on the project.

After the plans and specifications are more complete, PSI should be retained and provided the opportunity to review the final design plans and specifications to verify that our engineering recommendations have been properly incorporated into the design.

REFERENCES

<u>Reference 1:</u> Washington Department of Natural Recourses Interactive Geologic Map, http://www.dnr.wa.gov/researchscience/topics/geosciencesdata/pages/geology_portal.aspx


<u>Reference 2:</u> Sherrod, Brian L.; Blakely, Richard J.; Weaver, Craig S.; Kelsey, Harvey M.; Barnett, Elizabeth; Liberty, Lee; Meagher, Karen L.; Pape, Kristin, 2008, Finding concealed active faults--Extending the southern Whidbey Island fault across the Puget Lowland, Washington: Journal of Geophysical Research, v. 113,

<u>Reference 3:</u> Washington State Department of Ecology, Washington State Well Log Viewer, https://fortress.wa.gov/ecy/waterresources/map/WCLSWebMap/WellConstructionMapSearch.aspx

FIGURES

VICINITY MAP

SITE EXPLORATION LOCATION MAP








= SITE LOCATION

NOTES

Site underlay provided by Google Earth



In formation	PROJECT NAME:	DRAWN BY:	DATE:	FIGURE:
Information To Build On Engineering • Consulting • Testing	UPS Parking Lot 18001 NE Union Hill Road Redmond, Washington	MSP	February, 2016	1
20508 56th Ave W Sulte A	DESCRIPTION:	APPROVED BY:	PSI PROJECT NU	JMBER:
Lynwood, WA 98036 (425)409-2504	Vicinity Map	MSP	071	21335







Soil Boring Location

Infiltration Test Boring Location

NOTES Site underlay provided by UPS



Information To Build On Engineering · Consulting · Testing	PROJECT NAME: UPS Parking Lot 18001 NE Union Hill Road Redmond, Washington	DRAWN BY: MSP	DATE: February, 2016	FIGURE:
20508 56th Ave W Sulte A Lynwood, WA 98036 (425) 409-2504	DESCRIPTION: Site Exploration Map	APPROVED BY:	PSI PROJECT NU	JMBER: 21335

APPENDIX A

FIELD EXPLORATION PROGRAM

GENERAL NOTES

SOIL CLASSIFICATION CHART

BORING LOGS

FIELD EXPLORATION PROGRAM

General

We explored the site by drilling three soil borings (B-1 to B-3) to depths of approximately 16½ feet bgs and five infiltration test boring to a depth of approximately 3 feet using a trailer mounted drill rig, were advanced for this project. The locations of the borings and Soil and infiltration borings are shown on Figure 2. A representative of PSI's geotechnical staff was present during the explorations to record soil and groundwater conditions encountered in the exploration and to obtain soil samples for laboratory testing.

Sampling Procedures

Throughout the drilling operation, soil samples were obtained from the borings using a 2-inch OD Split Spoon in general conformance with guidelines presented in ASTM D1586, *Standard Test Method for Penetration Test and Split Barrel Sampling of Soils*. The samplers were driven into the soil a distance of 18 inches or to refusal with a 140-pound hammer free falling a distance of 30 inches. The sum of the blows required to drive the sampler in three 6-inch increments is provided in the boring logs. If the sampler met refusal, the number of inches driven and the number of blows is recorded. No sample are recovered from CPT's but data is available in this appendix.

The boring was drilled to observe the stratigraphy, density, and variability of subsurface soil conditions. Soil samples recovered from the explorations were sealed in airtight plastic jars to retain moisture and carefully transported to PSI's laboratory for additional examination and testing.

Field Classification

Soil samples were initially classified visually in the field. Consistency, color, relative moisture, degree of plasticity, peculiar odors and other distinguishing characteristics of the soil samples were noted. The terminology used in the soil and rock classifications and other modifiers are defined in the General Notes in this Appendix.

Exploration Logs

Summary boring log follows in this appendix. The left-hand portion of the boring log gives our interpretation of the soil encountered in the soil boring, sample locations and depths, and groundwater information. The right-hand portion of the log shows the results of the sample water contents, and other laboratory information.

The soil profile shown on the boring logs represent the conditions only at actual exploration location. Variations may occur and should be expected. The stratifications represent the approximate boundary between subsurface materials; the actual transition may be gradual.



GENERAL NOTES

SAMPLE IDENTIFICATION

The Unified Soil Classification System (USCS), AASHTO 1988 and ASTM designations D2487 and D-2488 are used to identify the encountered materials unless otherwise noted. Coarse-grained soils are defined as having more than 50% of their dry weight retained on a #200 sieve (0.075mm); they are described as: boulders, cobbles, gravel or sand. Fine-grained soils have less than 50% of their dry weight retained on a #200 sieve; they are defined as silts or clay depending on their Atterberg Limit attributes. Major constituents may be added as modifiers and minor constituents may be added according to the relative proportions based on grain size.

DRILLING AND SAMPLING SYMBOLS

SFA: Solid Flight Auger - typically 4" diameter flights, except where noted.

SS: Split-Spoon - 1 3/8" I.D., 2" O.D., except where noted.

HSA: Hollow Stem Auger - typically 3½" or 4½ I.D. ST: Shelby Tube - 3" O.D., except where noted.

openings, except where noted.

M.R.: Mud Rotary - Uses a rotary head with Bentonite

BS: Bulk Sample
PM: Pressuremeter

or Polymer Slurry CPT-U: Cone Penetrometer Testing with Pore-Pressure

R.C.: Diamond Bit Core Sampler Readings

H.A.: Hand Auger

P.A.: Power Auger - Handheld motorized auger

SOIL PROPERTY SYMBOLS

N: Standard "N" penetration: Blows per foot of a 140 pound hammer falling 30 inches on a 2-inch O.D. Split-Spoon.

N₆₀: A "N" penetration value corrected to an equivalent 60% hammer energy transfer efficiency (ETR)

Q.: Unconfined compressive strength, TSF

Q_o: Pocket penetrometer value, unconfined compressive strength, TSF

w%: Moisture/water content, %

LL: Liquid Limit, % PL: Plastic Limit, %

PI: Plasticity Index = (LL-PL),%

DD: Dry unit weight, pcf

▼.∇.▼ Apparent groundwater level at time noted

RELATIVE DENSITY OF COARSE-GRAINED SOILS ANGULARITY OF COARSE-GRAINED PARTICLES

Relative Density	N - Blows/foot	<u>Description</u>	Criteria
Very Loose	0 - 4 4 - 10	Angular:	Particles have sharp edges and relatively plane sides with unpolished surfaces
Loose Medium Dense	10 - 30	Subangular:	Particles are similar to angular description, but have rounded edges
Dense Very Dense	30 - 50 50 - 80	Subrounded:	Particles have nearly plane sides, but have well-rounded corners and edges
Extremely Dense	80+	Rounded:	Particles have smoothly curved sides and no edges

GRAIN-SIZE TERMINOLOGY

PARTICLE SHAPE

_	Component	Size Range	<u>Description</u>	<u>Criteria</u>
_	Boulders:	Over 300 mm (>12 in.)	Flat:	Particles with width/thickness ratio > 3
	Cobbles:	75 mm to 300 mm (3 in. to 12 in.)	Elongated:	Particles with length/width ratio > 3
Coarse	-Grained Gravel:	19 mm to 75 mm (¾ in. to 3 in.)	Flat & Elongated:	Particles meet criteria for both flat and
Fine	-Grained Gravel:	4.75 mm to 19 mm (No.4 to ¾ in.)		elongated
Coars	e-Grained Sand:	2 mm to 4.75 mm (No.10 to No.4)		

Medium-Grained Sand: 0.42 mm to 2 mm (No.40 to No.10) Fine-Grained Sand: 0.075 mm to 0.42 mm (No. 200 to No.40)

Sand: 0.075 mm to 0.42 mm (No. 200 to No.40)

Silt: 0.005 mm to 0.075 mm

Clay: <0.005 mm

RELATIVE PROPORTIONS OF FINES

Descriptive Term % Dry Weight

Trace: < 5%
With: 5% to 12%
Modifier: >12%



GENERAL NOTES

Description

CONSISTENCY OF FINE-GRAINED SOILS

MOISTURE CONDITION DESCRIPTION

Q _U - TSF	N - Blows/foot	Consistency
0 - 0.25	0 - 2	Very Soft
0.25 - 0.50	2 - 4	Soft
0.50 - 1.00	4 - 8	Medium Stiff
1.00 - 2.00	8 - 15	Stiff
2.00 - 4.00	15 - 30	Very Stiff
4.00 - 8.00	30 - 50	Hard
8.00+	50+	Very Hard

Dry: Absence of moisture, dusty, dry to the touch Moist: Damp but no visible water

Criteria

Wet: Visible free water, usually soil is below water table

RELATIVE PROPORTIONS OF SAND AND GRAVEL

Trace: < 15% With: 15% to 30%

Modifier: >30%

STRUCTURE DESCRIPTION

Description	Criteria	Description	Criteria
Stratified:	Alternating layers of varying material or color with layers at least 1/4-inch (6 mm) thick	Blocky:	Cohesive soil that can be broken down into small angular lumps which resist further breakdown
Laminated:	Alternating layers of varying material or color with		Inclusion of small pockets of different soils
	layers less than ¼-inch (6 mm) thick	Layer:	Inclusion greater than 3 inches thick (75 mm)
Fissured:	Breaks along definite planes of fracture with little resistance to fracturing	Seam:	Inclusion 1/8-inch to 3 inches (3 to 75 mm) thick extending through the sample
Slickensided:	Fracture planes appear polished or glossy, sometimes striated	Parting:	Inclusion less than 1/8-inch (3 mm) thick

SCALE OF RELATIVE ROCK HARDNESS ROCK BEDDING THICKNESSES

Q _∪ - TSF	<u>Consistency</u>	<u>Description</u>	Criteria
_ 0.F 40	F	Very Thick Bedded	Greater than 3-foot (>1.0 m)
2.5 - 10	Extremely Soft	Thick Bedded	1-foot to 3-foot (0.3 m to 1.0 m)
10 - 50	Very Soft	Medium Bedded	4-inch to 1-foot (0.1 m to 0.3 m)
50 - 250	Soft Madicus Hand	Thin Bedded	11/4-inch to 4-inch (30 mm to 100 mm)
250 - 525	Medium Hard	Very Thin Bedded	1/2-inch to 11/4-inch (10 mm to 30 mm)
525 - 1,050	Moderately Hard	Thickly Laminated	1/8-inch to 1/2-inch (3 mm to 10 mm)
1,050 - 2,600	Hard	Thinly Laminated	1/8-inch or less "paper thin" (<3 mm)
>2,600	Very Hard	•	, , , ,

ROCK VOIDS

Voids	Void Diameter	(Typically Sedimentary Rock)			
	<6 mm (<0.25 in)	Component	Size Range		
	6 mm to 50 mm (0.25 in to 2 in)	Very Coarse Grained	>4.76 mm		
•	50 mm to 600 mm (2 in to 24 in) >600 mm (>24 in)	Coarse Grained	2.0 mm - 4.76 mm		
,		Medium Grained	0.42 mm - 2.0 mm		
Cave	2000 Hilli (224 III)	Fine Grained	0.075 mm - 0.42 mm		
		Very Fine Grained	<0.075 mm		

ROCK QUALITY DESCRIPTION

DEGREE OF WEATHERING

GRAIN-SIZED TERMINOLOGY

Rock Mass Description Excellent Good Fair	RQD Value 90 -100 75 - 90 50 - 75	Slightly Weathered:	Rock generally fresh, joints stained and discoloration extends into rock up to 25 mm (1 in), open joints may contain clay, core rings under hammer impact.
Poor Very Poor	25 -50 Less than 25	Weathered:	Rock mass is decomposed 50% or less, significant portions of the rock show discoloration and weathering effects, cores cannot be broken by hand or scraped by knife.
		Highly Weathered:	Rock mass is more than 50% decomposed, complete discoloration of rock fabric, core may be extremely broken and gives clunk sound when struck by hammer, may be shaved with a knife.

Page 2 of 2

SOIL CLASSIFICATION CHART

NOTE: DUAL SYMBOLS ARE USED TO INDICATE BORDERLINE SOIL CLASSIFICATIONS

MAJOR DIVISIONS		SYMBOLS		TYPICAL	
Į IVI.	AJOR DIVISI	ONS	GRAPH	LETTER	DESCRIPTIONS
	GRAVEL AND	CLEAN GRAVELS		GW	WELL-GRADED GRAVELS, GRAVEL - SAND MIXTURES, LITTLE OR NO FINES
	GRAVELLY SOILS	(LITTLE OR NO FINES)		GP	POORLY-GRADED GRAVELS, GRAVEL - SAND MIXTURES, LITTLE OR NO FINES
COARSE GRAINED SOILS	MORE THAN 50% OF COARSE FRACTION	GRAVELS WITH FINES		GM	SILTY GRAVELS, GRAVEL - SAND - SILT MIXTURES
	RETAINED ON NO. 4 SIEVE	(APPRECIABLE AMOUNT OF FINES)		GC	CLAYEY GRAVELS, GRAVEL - SAND - CLAY MIXTURES
MORE THAN 50% OF MATERIAL IS	SAND AND	CLEAN SANDS		SW	WELL-GRADED SANDS, GRAVELLY SANDS, LITTLE OR NO FINES
LARGER THAN NO. 200 SIEVE SIZE	SANDY SOILS	(LITTLE OR NO FINES)		SP	POORLY-GRADED SANDS, GRAVELLY SAND, LITTLE OR NO FINES
	MORE THAN 50% OF COARSE FRACTION	SANDS WITH FINES		SM	SILTY SANDS, SAND - SILT MIXTURES
	PASSING ON NO. 4 SIEVE	(APPRECIABLE AMOUNT OF FINES)		sc	CLAYEY SANDS, SAND - CLAY MIXTURES
				ML	INORGANIC SILTS AND VERY FINE SANDS, ROCK FLOUR, SILTY OR CLAYEY FINE SANDS OR CLAYEY SILTS WITH SLIGHT PLASTICITY
FINE GRAINED SOILS	SILTS AND CLAYS	LIQUID LIMIT LESS THAN 50		CL	INORGANIC CLAYS OF LOW TO MEDIUM PLASTICITY, GRAVELLY CLAYS, SANDY CLAYS, SILTY CLAYS, LEAN CLAYS
00.20				OL	ORGANIC SILTS AND ORGANIC SILTY CLAYS OF LOW PLASTICITY
MORE THAN 50% OF MATERIAL IS SMALLER THAN NO. 200 SIEVE				МН	INORGANIC SILTS, MICACEOUS OR DIATOMACEOUS FINE SAND OR SILTY SOILS
SIZE	SILTS AND CLAYS	LIQUID LIMIT GREATER THAN 50		СН	INORGANIC CLAYS OF HIGH PLASTICITY
				ОН	ORGANIC CLAYS OF MEDIUM TO HIGH PLASTICITY, ORGANIC SILTS
н	GHLY ORGANIC S	SOILS	71/ 71/ 71/ 71/ 71/ 1/ 71/ 71/ 71/ 71/ 21/ 71/ 71/ 71/ 71/	РТ	PEAT, HUMUS, SWAMP SOILS WITH HIGH ORGANIC CONTENTS



(Psi)

Professional Service Industries, Inc. 20508 56th Avenue W, Suite A Lynnwood, WA 98036

Telephone: (425) 409-2504 Fax: (425) 582-8193

LOG OF BORING B-1

Sheet 1 of 1

PSI Job No.: 07121335 Project: UPS

Location: 18001 NE Union HIII Rd

Redmond, WA

Drilling Method: Hollow Stem Auger

Sampling Method: SS

Hammer Type: Manual Pulley

Boring Location:

Redmond	I, WA	Boring Location:					
Elevation (feet) Depth, (feet) Graphic Log Sample Type Sample No.	Re Re	USCS CIK	T Blows per 6-inch (\$\text{Amoisture, \(\text{Moisture, \) \) \}}}}} \end{supples \tag{\text{Moisture, \(\text{Moisture, \) \}}} \end{supples \tag{\text{Moisture, \(\text{Moisture, \(\text{Moisture, \(\text{Moisture, \) \}}} \end{supples \text{Moisture, \(\text{Moisture, \(\text{Moisture, \(\text{Moisture, \) \}}} \end{supples \end{supples \) \} \end{supples \text{Moisture, \(\text{Moisture, \(\text{Moisture, \) \}} \end{supples \) \} \end{supples \text{Moisture, \(\text{Moisture, \(\text{Moisture, \) \}}} \end{supples \text{Moisture, \(\text{Moisture, \(\text{Moisture, \) \}}} \end{supples \text{Moisture, \(\text{Moisture, \(\text{Moisture, \) \}}} \end{supples \text{Moisture, \(\text{Moisture, \) \end{supples \text{Moisture, \(\text{Moisture, \) \}}} \end{supples \text{Moisture, \(\text{Moisture, \) \}}} supples \te	ANDARD PENETRATION TEST DATA N in blows/ft ③ Moisture PL 25 LL 25 STRENGTH, tsf A Qu			
	Poorly-graded SAND with sil dark brown, moist, nonplastic (topsoil) Poorly graded SAND with sil moist, brown, medium dense rounded to sub rounded grav sand	c, with organics It and gravel: c, nonplastic,	6-8-7 N=15 10				
- 5 -	Poorly graded GRAVEL with brown, dense, nonplastic,	sand: moist,	5-5-7 N=12 5 × 9-13-17				
- 10 - 0°	Poorly-graded SAND with gr brown, dense, nonplastic, rounded gravel, sub rounded	unded to sub	N=30 3 × 16-28-27 N=55	>>®			
	Bottom of boring at 16 ft 6 inc water observed.	SP ches. No ground	7-14-25 N=39				
Completion Depth: Date Boring Started: Date Boring Completed: Logged By: Drilling Contractor:	Sunia Malolo Geologic Drill Split-S Rock	r Cutting Hand A Spoon Calif. Sa	uger Drill Rig: 1 ampler Remarks:	47.67547° -122.09304° Frailer Mounted			

psi

Professional Service Industries, Inc. 20508 56th Avenue W, Suite A Lynnwood, WA 98036 Telephone: (425) 409-2504 Fax: (425) 582-8193

LOG OF BORING B-2

Sheet 1 of 1

PSI Job No.: 07121335 Project: UPS

Location: 18001 NE Union HIII Rd

Redmond, WA

Drilling Method: Hollow Stem Auger

Sampling Method: SS

Hammer Type: Manual Pulley

Boring Location:

Reditiona, WA					Dorning Education	$ar{ar{ar{\Lambda}}}$								
Elevation (feet)	Depth, (feet)	Graphic Log	Sample Type	Sample No.	Recovery (inches)	Station: N/A Offset: N/A MATERIAL DESC	CRIPTION	USCS Classification	SPT Blows per 6-inch (SS)	Moisture, %	N in b X Moisture	T DATA lows/ft ⊚	PL LL 50 Qp 4.0	Additional Remarks
-	5 -	1 2 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			11	Poorly-graded SAND with silf dark brown, moist, nonplastic, (topsoil) Poorly graded SAND with silf moist, brown, medium dense nonplastic, rounded to sub rousub rounded sand	with organics and gravel: to dense,		1-5-6 N=11 10-17-20 N=37	10	×)	
-	-		X		3			SP-SM	11-12-12 N=24 8-12-14 N=26	9	×	0		
-	10 -				9				8-9-14 N=23	7	× (
-					8	Poorly graded GRAVEL with brown, dense, nonplastic, Bottom of boring at 16 ft 6 inc water observed.		GP	37-25-24 N=49	2	*			
Completi Date Bor Date Bor Logged E Drilling C	ing S ing C By:	Started		d:		16 Auger	Cutting 👺	Shelby Hand A Calif. S Texas (uger ampler	Long	ide: 47.6764 itude: -122.09 Rig: Trailer M arks:	301°		

Professional Service Industries, Inc. 20508 56th Avenue W, Suite A Lynnwood, WA 98036

LOG OF BORING B-3 Telephone: (425) 409-2504 Fax: (425) 582-8193 Sheet 1 of 1 WATER LEVELS Drilling Method: Hollow Stem Auger 07121335 PSI Job No.: **UPS** Sampling Method: SS Project: $\overline{\nabla}$ Hammer Type: Manual Pulley 18001 NE Union HIII Rd Location: Y Redmond, WA Boring Location: V Station: N/A SPT Blows per 6-inch (SS) STANDARD PENETRATION Offset: N/A TEST DATA Recovery (inches) **USCS Classification** Elevation (feet) N in blows/ft ⊚ Sample Type Graphic Log Depth, (feet) Sample No. % Moisture Moisture, MATERIAL DESCRIPTION Additional 11 Remarks STRENGTH, tsf Ж Qu Qp \blacktriangle Poorly-graded SAND with silt and gravel: dark brown, moist, nonplastic, with organics 15 11 8-12-10 (topsoil) N=22 Poorly graded SAND with silt and gravel: moist, brown, nonplastic, medium dense, rounded to sub rounded gravel, sub rounded 14 9 8-8-10 N=18 11 5 3-4-9 N = 13SP-SM 14 14 3-4-9 N=13 14 6-7-6 16 N=13 Poorly graded GRAVEL with sand: moist, brown, very dense, nonplastic,

Completion Depth: 15.0 ft Date Boring Started: 2/12/16 Date Boring Completed: 2/12/16 Logged By:

Drilling Contractor:

Sunia Malolo Geologic Drill

8

observed.

Sample Types: **Auger Cutting** Split-Spoon

Rock Core

Bottom of boring at 16.5 ft. No ground water

Shelby Tube Hand Auger Calif. Sampler Texas Cone

GΡ

Latitude: 47.67591° Longitude: -122.09319° Drill Rig: Trailer Mounted Remarks:

>>@

6

14-41-11

N=52

Professional Service Industries, Inc. 20508 56th Avenue W, Suite A Lynnwood, WA 98036 Telephone: (425) 409-2504 Fax: (425) 582-8193

LOG OF BORING I-1

PSI Job No.: 07121335 Project: UPS Location: 18001 NE Union HIII Rd Redmond, WA						Drilling Method: Hollow Stem Auger Sampling Method: Hammer Type: Boring Location:						WATER LEVELS			
Elevation (feet) Depth, (feet)	Graphic Log	Sample Log Sample Type Sample No. Recovery (inches) MATERIAL D			ESCRIPTION			Moisture, %	TES' N in bl X Moisture O STREN A Qu		PENETRATION T DATA lows/ft © PL 25 LL 25 LL 30 IGTH, tsf # Qp		Additional Remarks		
					Poorly-graded SAND with silt dark brown, moist, nonplastic, (topsoil) Poorly graded SAND with silt moist, brown, nonplastic, roun rounded gravel, sub rounded some subserved. Bottom boring 3 feet. No groun observed	and gravel: ded to sub sand	SP-SM						4.0		
Completion Depth: 3.0 ft Date Boring Started: 2/12/16 Date Boring Completed: 2/12/16 Logged By: Sunia Malolo Drilling Contractor: Geologic Drill			2/12/ 2/12/ Sunia	16 16 Auger A Malolo Split-S	Cutting 🖔	Shelby Hand A Calif. Sa Texas C	uger ampler	Longi	de: 47 tude: -1 Rig: Tra arks:	122.093	4°				

Professional Service Industries, Inc. 20508 56th Avenue W, Suite A Lynnwood, WA 98036

LOG OF BORING 1-2

Telephone: (425) 409-2504 Fax: (425) 582-8193 Sheet 1 of 1 WATER LEVELS Drilling Method: Hollow Stem Auger 07121335 PSI Job No.: **UPS** Sampling Method: Project: $\overline{\nabla}$ Hammer Type: 18001 NE Union HIII Rd Location: Ţ Redmond, WA Boring Location: V Station: N/A STANDARD PENETRATION Offset: N/A TEST DATA Recovery (inches) **USCS Classification** Elevation (feet) N in blows/ft ⊚ Sample Type Graphic Log Depth, (feet) Sample No. % Moisture Moisture, MATERIAL DESCRIPTION Additional 11 Remarks STRENGTH, tsf Qp Ж Qu \blacktriangle Poorly-graded SAND with silt and gravel: dark brown, moist, nonplastic, with organics 17. 11. Poorly graded SAND with silt and gravel: moist, brown, nonplastic, rounded to sub rounded gravel, sub rounded sand SP-SM Bottom boring 3 feet. No groundwater observed Completion Depth: Latitude: 47.67587° 3.0 ft Sample Types: Shelby Tube Longitude: -122.09342° Date Boring Started: 2/12/16 **Auger Cutting** Hand Auger Drill Rig: Trailer Mounted Date Boring Completed: 2/12/16 Split-Spoon Calif. Sampler Remarks: Logged By: Sunia Malolo Texas Cone Rock Core **Drilling Contractor:** Geologic Drill

(psi)

Professional Service Industries, Inc. 20508 56th Avenue W, Suite A Lynnwood, WA 98036 Telephone: (425) 409-2504 Fax: (425) 582-8193

LOG OF BORING I-3

	21335			Drilling Method: Hollow Stem Auger							WATER LEVELS			
Project: UPS Location: 1800		Inion I	HIII Rd	Sampling Method: Hammer Type:						$\bar{\Sigma}$				
	mond, \		I IIII Ku	Boring Location:						Ţ				
Elevation (feet) Depth, (feet) Graphic Log	Sample No.	Recovery (inches)	Station: N/A Offset: N/A MATERIAL DESC	RIPTION	USCS Classification		Moisture, %	× v	IDARD P TEST N in blo Moisture STRENC	*	PL LL 50	Additional Remarks		
			Poorly-graded SAND with silt dark brown, moist, nonplastic, v(topsoil) Poorly graded SAND with silt a moist, brown, nonplastic, round rounded gravel, sub rounded sclean gravel observed near base. Bottom boring 3 feet. No groun observed	and gravel: ded to sub and. Pocket of se.	SP-SM					0	4.0			
Completion Depth:		3.0 ft		/pes:	Shelby 7			de: 47		.42°				
Date Boring Started: Date Boring Complet		2/12/ ²	16 Auger C	_	Hand Au	uger	Longi Drill F	itude: -1 Rig: Tra	ı∠∠.093 ailer Mo	o4∠⁻ ounted				
Date Boring Complet Logged By:	.cu.		Split-Sp	ooon 🏢	Calif. Sa	ampler	Rema							
Drilling Contractor:		Sunia Malolo Geologic Drill Rock		ore	Texas C	Cone								

Professional Service Industries, Inc. 20508 56th Avenue W, Suite A Lynnwood, WA 98036 Telephone: (425) 409-2504 Fax: (425) 582-8193

LOG OF BORING I-4

PSI Job No.: 07121335				335	•	,	Drilling Method: Hollow Stem Auger						V	/ATEF	R LEVELS
Project Location			001	NE ond,		HIII Rd	Sampling Method: Hammer Type: Boring Location:								
Elevation (feet)	Depth, (feet)	Graphic Log	Sample Type	Sample No.	Recovery (inches)	Station: N/A Offset: N/A MATERIAL DESC	CRIPTION	USCS Classification		Moisture, %	× N	TEST N in blo Noisture	PENETRA DATA DWS/ft DWS/ft	PL LL 50	Additional Remarks
Comple	- 0 -				3.0 ft	Poorly-graded SAND with silt dark brown, moist, nonplastic, (topsoil) Poorly graded SAND with silt moist, brown, nonplastic, roun rounded gravel, sub rounded sclean gravel observed near based on the served observed. Bottom boring 3 feet. No ground observed.	and gravel: ded to subsand. Pocket of se.	SP-SM			de: 47		2.0	4.0	
Date Be Date Be Logged Drilling	oring (oring (I By:	Started Compl	d: eteo	d:	2/12/ 2/12/ Sunia	16 Auger	Cutting 👺	Shelby Hand A Calif. Sa Texas (uger ampler	Longi	itude: - Rig: Tra	122.092	287°		

Professional Service Industries, Inc. 20508 56th Avenue W, Suite A Lynnwood, WA 98036 Telephone: (425) 409-2504 Fax: (425) 582-8193

LOG OF BORING I-5

PSI Job No.: 07121335 Project: UPS Location: 18001 NE Union HIII Rd Redmond, WA						Sampling Method: Sampling Method Hammer Type: Boring Location	ıger			Ā Ā Ā	LEVELS			
Elevation (feet) Depth, (feet)	Graphic Log Sample Type Sample No. Recovery (inches) WALERIAL D			ESCRIPTION		USCS Classification		TES' N in bl Moisture STREN		PENETRATION T DATA lows/ft © PL DESTRUCTION 1000000000000000000000000000000000000		Additional Remarks		
				2.0.4	Poorly-graded SAND with silt dark brown, moist, nonplastic, (topsoil) Poorly graded SAND with silt moist, brown, nonplastic, roun rounded gravel, sub rounded sclean gravel observed near base observed. Bottom boring 3 feet. No ground observed	and gravel: ded to sub sand. Pocket of ise.	SP-SM				.67575		4.0	
Completion Depth: 3.0 ft Date Boring Started: 2/12/16 Date Boring Completed: 2/12/16 Logged By: Sunia Male Drilling Contractor: Geologic I			2/12/ 2/12/ Sunia	16 16 Auger A Malolo Split-S	Cutting poon	Shelby Hand A Calif. Sa Texas C	uger ampler	Longi	itude: -′ Rig: Tra	.67575 122.093 ailer Mo	04°			

APPENDIX B LABORATORY TESTING PROGRAM LABORATORY TEST RESULTS

Laboratory Testing Program and Procedures

General

Soil samples obtained during the field explorations were examined in our laboratory. The physical characteristics of the samples were noted and the field classifications were modified where necessary in accordance with terminology presented the General Notes included in this appendix.

Representative samples were selected during the course of the examination for further testing. The testing procedures and results of the tests are summarized below. The phrase "In general accordance with guidelines presented in..." means that certain local and common descriptive practices and methodologies have been followed.

Visual-Manual Classification

The soil samples were classified in general accordance with guidelines presented in ASTM D2488, Standard Practice for Description and Identification of Soils (Visual-Manual Procedure). Certain terminology incorporating current local engineering practice, as provided in the Soil Classification Chart included with or in lieu of ASTM terminology. The term which best described the major portion of the sample was used in determining the soil type (that is, gravel, sand, silt or clay).

Moisture Content

Natural moisture content determinations were made on all samples. The natural moisture content is defined as the ratio of the weight of water to dry weight of soil, expressed as a percentage. The results of the moisture content determinations are presented on the boring logs in this appendix.

Grain Size Analysis

Select samples from the borings were analyzed for grain size in general conformance with ASTM C 136 and ASTM C117. In general, samples were oven dried, weighed then washed over a #200 sieve to remove silt and clay sized particles and then dried again. The samples were separated through a series of sieves of progressively smaller openings for determination of particle size distribution. The material passing and/or retained on each sieve was recorded as a percent of the total sample weight. The results of the sieve analysis are depicted in this Appendix.


California Bearing Ratio (CBR)

The CBR (ASTM D4429), involve compacting a sample material into several molds at various levels of compaction and saturating them for a period of 96 hours. After saturation the material is placed into a machine that forces a two-inch diameter rod into the soil measurements of the depth of embedment and force exerted on the soil to penetrate the soil to these depths are recorded and then plotted to determine the CBR value at various levels of compactive effort.

Modified Proctor

A sample of soil was analyzed using moisture density test ASTM D1557. The test involves compacting soil into a four or six-inch diameter mold using a ten-pound hammer falling 18 inches for specified number of times in five lifts. The test is rerun at multiple moisture contents and the densities and moisture contents are plotted to determine the maximum dry density and moisture content of the material.

PARTICLE SIZE ANALYSIS - ASTM C136/C117



PARTICLE SIZE IN MILLIMETERS

		Coarse	Fine	Coarse	Medium	Fine	Silt	Clay
BOULDERS	COBBLES	GRAVEL		SAND			FINE GRAINED	

% Gravel	% Sand	% Fines	PL = NP
15.3%	81.0%	3.7%	
13.376	01.070	3.7 /6	LL = NP
Soil Classification			
Poorly Graded SAND with Gravel			PI = NP

Exploration	Sample	Depth(feet)	Moisture	Reviewed	USCS Symbol
B-1		5 feet	7.6	MSP	SP




07121235

PROJECT NAME:

UPS, Redmond

PARTICLE SIZE ANALYSIS - ASTM C136/C117



PARTICLE SIZE IN MILLIMETERS

		Coarse	Fine	Coarse	Medium	Fine	Silt	Clay
BOULDERS	COBBLES	GRAVEL		SAND			FINE GRAINED	

% Gravel	% Sand	% Fines	PL = NP		
40.0%	54.5%	5.4%			
40.070	04.070	3.470	LL = NP		
Soil Classification					
Poorly Graded SAND with Silt and Gravel			PI = NP		

Exploratio	Sample	Depth	Moisture	Reviewed	USCS Symbol
Composite B-1, B-2		Cuttings 0.5-3 feet	2.3	MSP	SP-SM



07121335

PROJECT NAME:

UPS, Redmond



Professional Service Industries, Inc. 20508 56th Avenue, Suite A Lynnwood, WA 98036

Phone: (425) 409-2504 Fax: (425) 582-8193

California Bearing Ratio Report

UNITED PARCEL SERVICE 6707 NORTH BASIN AVENUE

PORTLAND, OR 97217

Project: UPS PARKING LOT REDMOND

Report No: CBR:07121335-1-S2 Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the

PSI scope of engagement.

Approved Signatory: Michael Place (Project Engineer Date of Issue: 2/24/2016

Sample Details

Sample ID: 07121335-1-S2 Date Sampled: 1/27/2016

Sampling Method: Material:


Location: Tested By: (unknown)

Source:

Specification:

CC:


Date Tested:



Overall Results

ASTM D 1883

Test Results				
Blows	10	25	56	
Comp. Eff.	ASTM D 1557	ASTM D 1557	ASTM D 1557	
Initial MC (%)	8.9	9.3	8.8	
MC of Top 1in (%)	8.9	9.3	8.8	
MC After (%)	8.9	9.3	8.8	
DD Before (lb/ft³)	124.20	126.81	133.68	
DD After (lb/ft³)	124.20	126.32	135.04	
CBR (%)	15.5	31.2	70.3	
% MDD	92.8	94.8	99.9	
Sample Condition	soaked	soaked	soaked	
Surcharge (lb)				
Swell (%)				
Oversize (%)				



Comments



Professional Service Industries, Inc. 20508 56th Avenue, Suite A Lynnwood, WA 98036

Phone: (425) 409-2504 Fax: (425) 582-8193

Proctor Report

Client: UNITED PARCEL SERVICE 6707 NORTH BASIN AVENUE

PORTLAND, OR 97217

Project: UPS PARKING LOT REDMOND

Report No: PTR:07121335-1-S2

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service

the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Mobil flav

Industries, Inc. If a non-compliance appears on this report, to the extent that

Approved Signatory: Michael Place (Project Engineer)
Date of Issue: 2/24/2016

Sample Details

Sample ID: 07121335-1-S2 Sampled By: Michael Place

Material:

Actorial:


Location:

Date Sampled: 1/27/2016

Specification: no specifications

Sampling Method:

Tested By: (unknown)



CC:

_		
	Test Results	
١	ASTM D 1557	
	Maximum Dry Density (lbf/ft³):	133.8
١	Optimum Moisture Content (%):	8.6
١	Method:	С
١	Preparation Method:	
١	Retained Sieve 3/8" (9.5mm) (%):	47
١	Retained Sieve 3/4" (19mm) (%):	18
١	Passing Sieve 3/8" (9.5mm) (%):	53
١	Passing Sieve 3/4" (19mm) (%):	82
١	Specific Gravity (Oversize):	2.64
١	ASTM D 4718	
١	Corrected Maximum Dry Density (lbf/ft³):	138.5
١	Corrected Optimum Moisture Content	7.2
١	(%):	
١		
١		
١		
١		
١		
١		
١		
١		
١		

Comments

WWHM2012 PROJECT REPORT

General Model Information

Project Name: UPS REDMOND

Site Name: Site Address:

City:

Report Date: 2/1/2017 Gage: Seatac

 Data Start:
 1948/10/01

 Data End:
 2009/09/30

 Timestep:
 15 Minute

Precip Scale: 1.00

Version Date: 2016/02/25

Version: 4.2.12

POC Thresholds

Low Flow Threshold for POC1: 50 Percent of the 2 Year

High Flow Threshold for POC1: 50 Year

UPS REDMOND 2/1/2017 9:56:07 AM Page 2

Landuse Basin Data Predeveloped Land Use

Basin 1

Bypass: No

GroundWater: No

Pervious Land Use acre C, Forest, Mod 1.32 C, Forest, Steep 1.32

Pervious Total 2.64

Impervious Land Use acre

Impervious Total 0

Basin Total 2.64

Element Flows To:

Surface Interflow Groundwater

UPS REDMOND 2/1/2017 9:56:07 AM Page 3

Mitigated Land Use

Basin 1

Bypass: No

GroundWater: No

Pervious Land Use acre C, Lawn, Flat 0.27 C, Lawn, Mod C, Lawn, Steep 0.17 0.15

Pervious Total 0.59

Impervious Land Use PARKING MOD acre 2.06

Impervious Total 2.06

Basin Total 2.65

Element Flows To:

Groundwater Surface Interflow

Vault 1 Vault 1

Routing Elements Predeveloped Routing

Mitigated Routing

Vault 1

Width: 81.8916843467132 ft. Length: 81.8916843467132 ft.

Depth: 6.89 ft.

Discharge Structure

Riser Height: 5.89 ft. Riser Diameter: 18 in.

Orifice 1 Diameter: 1.03 in. Elevation:0 ft.

Orifice 2 Diameter: 1.55 in. Elevation:3.53863 ft. Orifice 3 Diameter: 0.93 in. Elevation:4.0275 ft.

Element Flows To:


Outlet 1 Outlet 2


Vault Hydraulic Table

Stage(feet)	Area(ac.)	Volume(ac-ft.)	Discharge(cfs) Infilt(cfs)
0.0000	0.154	0.000	0.000	0.000
0.0766	0.154	0.011	0.008	0.000
0.1531	0.154	0.023	0.011	0.000
0.2297	0.154	0.035	0.013	0.000
0.3062	0.154	0.047	0.015	0.000
0.3828	0.154	0.058	0.017	0.000
0.4593	0.154	0.070	0.019	0.000
0.5359	0.154	0.082	0.021	0.000
0.6124	0.154	0.094	0.022	0.000
0.6890	0.154	0.106	0.023	0.000
0.7656	0.154	0.117	0.025	0.000
0.8421	0.154	0.129	0.026	0.000
0.9187	0.154	0.141	0.027	0.000
0.9952	0.154	0.153	0.028	0.000
1.0718	0.154	0.165	0.029	0.000
1.1483	0.154	0.176	0.030	0.000
1.2249	0.154	0.188	0.031	0.000
1.3014	0.154	0.200	0.032	0.000
1.3780	0.154	0.212	0.033	0.000
1.4546	0.154	0.223	0.034	0.000
1.5311	0.154	0.235	0.035	0.000
1.6077	0.154	0.247	0.036	0.000
1.6842	0.154	0.259	0.037	0.000
1.7608	0.154	0.271	0.038	0.000
1.8373	0.154	0.282	0.039	0.000
1.9139	0.154	0.294	0.039	0.000
1.9904	0.154	0.306	0.040	0.000
2.0670	0.154	0.318	0.041	0.000
2.1436	0.154	0.330	0.042	0.000
2.2201	0.154	0.341	0.042	0.000
2.2967	0.154	0.353	0.043	0.000
2.3732	0.154	0.365	0.044	0.000
2.4498	0.154	0.377	0.045	0.000
2.5263	0.154	0.388	0.045	0.000
2.6029	0.154	0.400	0.046	0.000
2.6794	0.154	0.412	0.047	0.000
2.7560	0.154	0.424	0.047	0.000
2.8326	0.154	0.436	0.048	0.000

2.9091 2.9857 3.0622 3.1388 3.2153 3.2919 3.3684 3.4450 3.5216 3.5981 3.6747 3.7512 3.8278 3.9043 3.9809 4.0574	0.154 0.154 0.154 0.154 0.154 0.154 0.154 0.154 0.154 0.154 0.154 0.154 0.154	0.447 0.459 0.471 0.483 0.495 0.506 0.518 0.530 0.542 0.553 0.565 0.577 0.589 0.601 0.612 0.624	0.049 0.049 0.050 0.051 0.051 0.052 0.053 0.054 0.070 0.079 0.085 0.091 0.096 0.100 0.109	0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000
4.1340	0.154	0.636	0.116	0.000
4.2106	0.154	0.648	0.122	0.000
4.2871	0.154	0.660	0.128	0.000
4.3637	0.154	0.671	0.133	0.000
4.4402	0.154	0.683	0.137	0.000
4.5168	0.154	0.695	0.142	0.000
4.5933	0.154	0.707	0.146	0.000
4.6699	0.154	0.718	0.150	0.000
4.7464	0.154	0.730	0.154	0.000
4.8230	0.154	0.742	0.158	0.000
4.8996	0.154	0.754	0.161	0.000
4.9761	0.154	0.766	0.165	0.000
5.0527	0.154	0.777	0.168	0.000
5.1292	0.154	0.789	0.172	0.000
5.2058	0.154	0.801	0.175	0.000
5.2823	0.154	0.813	0.178	0.000
5.3589	0.154	0.825	0.181	0.000
5.4354	0.154	0.836	0.184	0.000
5.5120	0.154	0.848	0.187	0.000
5.5886	0.154	0.860	0.190	0.000
5.6651	0.154	0.872	0.193	0.000
5.7417	0.154	0.884	0.196	0.000
5.8182	0.154	0.895	0.199	0.000
5.8948	0.154	0.907	0.207	0.000
5.9713	0.154	0.919	0.573	0.000
6.0479	0.154	0.931	1.199	0.000
6.1244	0.154	0.942	1.978	0.000
6.2010	0.154	0.954	2.839	0.000
6.2776	0.154	0.966	3.710	0.000
6.3541	0.154	0.978	4.518	0.000
6.4307	0.154	0.990	5.203	0.000
6.5072	0.154	1.001	5.726	0.000
6.5838	0.154	1.013	6.093	0.000
6.6603	0.154	1.025	6.447	0.000
6.7369	0.154	1.037	6.751	0.000
6.8134	0.154	1.049	7.042	0.000
6.8900	0.154	1.060	7.321	0.000
6.9666 7.0431	0.154 0.000	1.072 0.000	7.589 7.849	0.000 0.000 0.000

Analysis Results POC 1





+ Predeveloped x Mitigated

Predeveloped Landuse Totals for POC #1

Total Pervious Area: 2.64
Total Impervious Area: 0

Mitigated Landuse Totals for POC #1 Total Pervious Area: 0.59 Total Impervious Area: 2.06

Flow Frequency Method: Log Pearson Type III 17B

Flow Frequency Return Periods for Predeveloped. POC #1

 Return Period
 Flow(cfs)

 2 year
 0.098653

 5 year
 0.158558

 10 year
 0.196562

 25 year
 0.241385

 50 year
 0.27223

 100 year
 0.300912

Flow Frequency Return Periods for Mitigated. POC #1

 Return Period
 Flow(cfs)

 2 year
 0.060687

 5 year
 0.098169

 10 year
 0.130283

 25 year
 0.180606

 50 year
 0.226152

 100 year
 0.279495

Annual Peaks

Annual Peaks for Predeveloped and Mitigated. POC #1

Year	Predeveloped	Mitigated
1949	0.112	0.041
1950	0.126	0.052
1951	0.201	0.166
1952	0.070	0.037
1953	0.054	0.046
1954	0.078	0.048
1955	0.138	0.048
1956	0.107	0.071
1957	0.095	0.048
1958	0.095	0.050

1959 1960 1961 1962 1963 1964 1965 1966 1967 1968 1970 1971 1972 1973 1974 1975 1976 1977 1978 1979 1980 1981 1982 1983 1984 1985 1988 1989 1990 1991 1992 1993 1994 1995 1996 1997 1998 1999 1999 1999 2000 2001 2005 2006	0.080 0.145 0.078 0.053 0.071 0.093 0.066 0.062 0.147 0.082 0.076 0.158 0.075 0.076 0.116 0.080 0.013 0.073 0.040 0.185 0.060 0.138 0.104 0.068 0.038 0.171 0.150 0.062 0.037 0.037 0.040 0.055 0.076 0.150 0.099 0.125 0.076 0.089 0.015	0.043 0.150 0.052 0.037 0.048 0.049 0.078 0.045 0.051 0.046 0.050 0.050 0.047 0.049 0.042 0.051 0.049 0.044 0.049 0.044 0.049 0.043 0.051 0.052 0.052 0.053
2004	0.162	0.178

Ranked Annual Peaks

adi i dano						
Ranked Annual Peaks for Predeveloped and Mitigated. POC #1						
Predeveloped	Mitigated					
0.3372	0.2792					
0.3264	0.1783					
0.2551	0.1747					
	Peaks for Prede Predeveloped 0.3372 0.3264	Peaks for Predeveloped and Mitigated. Predeveloped Mitigated 0.3372 0.2792 0.3264 0.1783				

4567891011234567891011234567890312334567894445678955555555555555555555555555555555555	0.2294 0.2012 0.1924 0.1880 0.1865 0.1852 0.1711 0.1621 0.1575 0.1511 0.1504 0.1473 0.1445 0.1383 0.1380 0.1258 0.1245 0.1159 0.1145 0.1096 0.1071 0.1036 0.0992 0.0954 0.0951 0.0952 0.0888 0.0839 0.0824 0.0805 0.0798 0.0758 0.0758 0.0758 0.0758 0.0759 0.0760 0.0763 0.0760 0.0763 0.0760 0.0763 0.0760 0.0758 0.0755 0.0760 0.0763 0.0758 0.0755 0.0555 0.0555 0.0555	0.1659 0.1640 0.1510 0.1497 0.1485 0.1408 0.1401 0.1396 0.1304 0.1275 0.1253 0.1018 0.0939 0.0888 0.0782 0.0712 0.0631 0.0539 0.0532 0.0524 0.0522 0.0516 0.0511 0.0509 0.0505 0.0504 0.0494 0.0494 0.0494 0.0494 0.0494 0.0494 0.0493 0.0483 0.0483 0.0483 0.0483 0.0483 0.0462 0.0458 0.0456 0.0458 0.0456 0.0458 0.0458 0.0458 0.0458 0.0427 0.0425 0.0424 0.0423 0.0411 0.0406 0.0369 0.0367 0.0365

UPS REDMOND 2/1/2017 9:56:48 AM Page 10

Duration Flows

The Facility PASSED

10.0493	Elow(ofc)	Predev	Mit	Percentage	Pass/Fail
0.0516 12189 8382 68 Pass 0.0538 11221 5356 47 Pass 0.0561 9965 3918 39 Pass 0.0583 9163 3837 41 Pass 0.0606 8427 3758 44 Pass 0.0628 7798 3685 47 Pass 0.0651 6992 3585 51 Pass 0.0666 6027 3454 57 Pass 0.0718 5619 3362 59 Pass 0.0763 4678 3084 65 Pass 0.0771 5033 3193 63 Pass 0.0763 4678 3084 65 Pass 0.0763 4678 3084 65 Pass 0.07741 5033 3193 63 Pass 0.0784 4346 2988 68 Pass 0.0880 4100 2887 70 <	Flow(cfs)				
0.0538 11221 5356 47 Pass 0.0561 9965 3918 39 Pass 0.0583 9163 3837 41 Pass 0.0606 8427 3758 44 Pass 0.0651 6992 3585 47 Pass 0.0651 6992 3585 51 Pass 0.0673 6485 3516 54 Pass 0.0673 6485 3516 54 Pass 0.0718 5619 3362 59 Pass 0.0741 5033 3193 63 Pass 0.0763 4678 3084 65 Pass 0.0766 4346 2988 68 Pass 0.0763 4678 3084 65 Pass 0.0844 298 298 68 Pass 0.0844 3506 2586 73 Pass 0.0921 2845 2199 77 P					
0.0561 9965 3918 39 Pass 0.0583 9163 3837 41 Pass 0.0606 8427 3758 44 Pass 0.0628 7798 3685 47 Pass 0.0651 6992 3585 51 Pass 0.0673 6485 3516 54 Pass 0.0673 6485 3516 54 Pass 0.0741 5033 3193 63 Pass 0.0763 4678 3084 65 Pass 0.0786 4346 2988 68 Pass 0.0808 4100 2887 70 Pass 0.0813 3728 2704 72 Pass 0.0854 3506 2586 73 Pass 0.0814 2671 2093 78 Pass 0.0921 2845 2199 77 Pass 0.0966 2513 2003 79					
0.0583 9163 3837 41 Pass 0.0606 8427 3758 44 Pass 0.0628 7798 3685 47 Pass 0.0651 6992 3585 51 Pass 0.0673 6485 3516 54 Pass 0.0696 6027 3454 57 Pass 0.0741 5033 3193 63 Pass 0.0763 4678 3084 65 Pass 0.0764 4346 2988 68 Pass 0.0786 4346 2988 68 Pass 0.0808 4100 2887 70 Pass 0.0854 3506 2586 73 Pass 0.0876 3294 2460 74 Pass 0.0899 3104 2348 75 Pass 0.0921 2845 2199 77 Pass 0.0966 2513 2003 79					
0.0606 8427 3758 44 Pass 0.0628 7798 3685 47 Pass 0.0661 6992 3585 51 Pass 0.0673 6485 3516 54 Pass 0.0718 5619 3362 59 Pass 0.0741 5033 3193 63 Pass 0.0763 4678 3084 65 Pass 0.0786 4346 2988 68 Pass 0.0831 3728 2704 72 Pass 0.0834 3506 2586 73 Pass 0.0876 3294 2460 74 Pass 0.0899 3104 2348 75 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.1011 2107 1709 81 Pass 0.1024 2671 2093 79					
0.0628 7798 3685 47 Pass 0.0651 6992 3585 51 Pass 0.0673 6485 3516 54 Pass 0.0696 6027 3454 57 Pass 0.0748 5619 3362 59 Pass 0.0763 4678 3084 65 Pass 0.0786 4346 2988 68 Pass 0.0808 4100 2887 70 Pass 0.0854 3506 2586 73 Pass 0.0876 3294 2460 74 Pass 0.0876 3294 2460 74 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0944 2671 2093 78 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84					
0.0651 6992 3585 51 Pass 0.0673 6485 3516 54 Pass 0.0696 6027 3454 57 Pass 0.0718 5619 3362 59 Pass 0.0763 4678 3084 65 Pass 0.0786 4346 2988 68 Pass 0.0808 4100 2887 70 Pass 0.0831 3728 2704 72 Pass 0.0854 3506 2586 73 Pass 0.0876 3294 2460 74 Pass 0.0899 3104 2348 75 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1026 1829 1605 87					
0.0673 6485 3516 54 Pass 0.0696 6027 3454 57 Pass 0.0718 5619 3362 59 Pass 0.0763 4678 3084 65 Pass 0.0786 4346 2988 68 Pass 0.0808 4100 2887 70 Pass 0.0831 3728 2704 72 Pass 0.0854 3506 2586 73 Pass 0.0876 3294 2460 74 Pass 0.0921 2845 2199 77 Pass 0.0921 2845 2199 77 Pass 0.0966 2513 2003 79 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1079 1687 1560 92					
0.0696 6027 3454 57 Pass 0.0718 5619 3362 59 Pass 0.0741 5033 3193 63 Pass 0.0763 4678 3084 65 Pass 0.0786 4346 2988 68 Pass 0.0808 4100 2887 70 Pass 0.0831 3728 2704 72 Pass 0.0854 3506 2586 73 Pass 0.0876 3294 2460 74 Pass 0.0876 3294 2460 74 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0966 2513 2003 79 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1079 1687 1560 92					
0.0718 5619 3362 59 Pass 0.0763 4678 3084 65 Pass 0.0786 4346 2988 68 Pass 0.0808 4100 2887 70 Pass 0.0831 3728 2704 72 Pass 0.0854 3506 2586 73 Pass 0.0876 3294 2460 74 Pass 0.0899 3104 2348 75 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0944 2671 2093 79 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1079 1687 1560 92 Pass 0.1101 1532 1484 96					
0.0741 5033 3193 63 Pass 0.0763 4678 3084 65 Pass 0.0786 4346 2988 68 Pass 0.0808 4100 2887 70 Pass 0.0831 3728 2704 72 Pass 0.0876 3294 2460 74 Pass 0.0876 3294 2460 74 Pass 0.0871 2845 2199 77 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0966 2513 2003 79 Pass 0.0966 2513 2003 79 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92					
0.0763 4678 3084 65 Pass 0.0786 4346 2988 68 Pass 0.0808 4100 2887 70 Pass 0.0831 3728 2704 72 Pass 0.0854 3506 2586 73 Pass 0.0876 3294 2460 74 Pass 0.0899 3104 2348 75 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0966 2513 2003 79 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1104 1343 1368 101 <td< td=""><td></td><td></td><td></td><td></td><td></td></td<>					
0.0786 4346 2988 68 Pass 0.0808 4100 2887 70 Pass 0.0831 3728 2704 72 Pass 0.0876 3294 2460 74 Pass 0.0876 3294 2460 74 Pass 0.0899 3104 2348 75 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0944 2671 2093 79 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1104 1425 1424 99 Pass 0.1104 1343 1368 101 <td< td=""><td></td><td></td><td></td><td></td><td></td></td<>					
0.0808 4100 2887 70 Pass 0.0831 3728 2704 72 Pass 0.0876 3294 2460 74 Pass 0.0899 3104 2348 75 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0966 2513 2003 79 Pass 0.0966 2513 2003 79 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1079 1687 1560 92 Pass 0.1079 1687 1560 92 Pass 0.1104 1425 1424 99 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1214 1052 1135 107 <t< td=""><td></td><td>4346</td><td></td><td></td><td></td></t<>		4346			
0.0831 3728 2704 72 Pass 0.0854 3506 2586 73 Pass 0.0876 3294 2460 74 Pass 0.0899 3104 2348 75 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0966 2513 2003 79 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1104 1425 1424 99 Pass 0.1124 1425 1424 99 Pass 0.1169 1255 1305 103 Pass 0.1214 1052 1135 107 <t< td=""><td></td><td></td><td></td><td></td><td></td></t<>					
0.0854 3506 2586 73 Pass 0.0876 3294 2460 74 Pass 0.0899 3104 2348 75 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0966 2513 2003 79 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1079 1687 1560 92 Pass 0.1079 1687 1560 92 Pass 0.1101 1532 1484 96 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 <					
0.0876 3294 2460 74 Pass 0.0899 3104 2348 75 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0986 2513 2003 79 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1079 1687 1560 92 Pass 0.1124 1425 1424 99 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1214 1052 1135 107 Pass 0.1224 1052 1135 107 <					
0.0899 3104 2348 75 Pass 0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0966 2513 2003 79 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1079 1687 1560 92 Pass 0.1101 1532 1484 96 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 <					
0.0921 2845 2199 77 Pass 0.0944 2671 2093 78 Pass 0.0966 2513 2003 79 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1101 1532 1484 96 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1146 1343 1368 101 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1259 949 993 104 <					
0.0944 2671 2093 78 Pass 0.0966 2513 2003 79 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1079 1687 1560 92 Pass 0.1101 1532 1484 96 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 P					
0.0966 2513 2003 79 Pass 0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1101 1532 1484 96 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1169 1255 1305 103 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pa					
0.0989 2357 1910 81 Pass 0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1101 1532 1484 96 Pass 0.1124 1425 1424 99 Pass 0.1124 1425 1424 99 Pass 0.1169 1255 1305 103 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass<					
0.1011 2107 1709 81 Pass 0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1101 1532 1484 96 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1146 1343 1368 101 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1259 949 993 104 Pass 0.1304 851 811 95 Pass 0.1304 851 811 95 Pass 0.1349 765 722 94 Pass 0.1394 669 601 89 Pass<					
0.1034 1962 1655 84 Pass 0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1101 1532 1484 96 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1169 1255 1305 103 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1259 949 993 104 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0					
0.1056 1829 1605 87 Pass 0.1079 1687 1560 92 Pass 0.1101 1532 1484 96 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1169 1255 1305 103 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1259 949 993 104 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1					
0.1079 1687 1560 92 Pass 0.1101 1532 1484 96 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1169 1255 1305 103 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1236 995 1066 107 Pass 0.1259 949 993 104 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1416 638 548 85 Pass					
0.1101 1532 1484 96 Pass 0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1169 1255 1305 103 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1259 949 993 104 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1506 487 373 76 Pass 0.1529<					
0.1124 1425 1424 99 Pass 0.1146 1343 1368 101 Pass 0.1169 1255 1305 103 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1259 949 993 104 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1506 487 373 76 Pass 0.1551 <td></td> <td></td> <td></td> <td></td> <td></td>					
0.1146 1343 1368 101 Pass 0.1169 1255 1305 103 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1259 949 993 104 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1574					
0.1169 1255 1305 103 Pass 0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1259 949 993 104 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1441 559 447 79 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1574 368 293 79 Pass 0.1597					
0.1191 1127 1207 107 Pass 0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1259 949 993 104 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1551 396 318 80 Pass					
0.1214 1052 1135 107 Pass 0.1236 995 1066 107 Pass 0.1259 949 993 104 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1642 272 206 75 Pass					
0.1236 995 1066 107 Pass 0.1259 949 993 104 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1642 272 206 75 Pass					
0.1259 949 993 104 Pass 0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1642 272 206 75 Pass					
0.1281 892 868 97 Pass 0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1642 272 206 75 Pass					
0.1304 851 811 95 Pass 0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1326 807 768 95 Pass 0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1349 765 722 94 Pass 0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1371 706 649 91 Pass 0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1394 669 601 89 Pass 0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1416 638 548 85 Pass 0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1439 602 516 85 Pass 0.1461 559 447 79 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1461 559 447 79 Pass 0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1484 525 414 78 Pass 0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1506 487 373 76 Pass 0.1529 441 345 78 Pass 0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1529 441 345 78 Pass 0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1551 396 318 80 Pass 0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1574 368 293 79 Pass 0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1597 336 270 80 Pass 0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1619 310 240 77 Pass 0.1642 272 206 75 Pass					
0.1642 272 206 75 Pass					
- 1 3133			184	73	

0.1687	225	171	76	Pass
0.1709	202	152	75	Pass
0.1732	175	129	73	Pass
0.1754	154	108	70	Pass
0.1777	139	86	61	Pass
0.1799	129	70	54	Pass
0.1822	115	63	54	Pass
0.1844	99	58	58	Pass
0.1867	89	55	61	Pass
0.1889	79	49	62	Pass
0.1912	68	43	63	Pass
0.1934	57	40	70	Pass
0.1957	53	36	67	Pass
0.1979	49	29	59	Pass
0.2002	44	19	43	Pass
0.2024	42	16	38	Pass
0.2047	41	15	36	Pass
0.2069	40	12	30	Pass
0.2092	35	6	17	Pass
0.2114	33	6	18	Pass
0.2137	31	6	19	Pass
0.2159	29	5	17	Pass
0.2182	27	5	18	Pass
0.2204	25	5	20	Pass
0.2227	22	5	22	Pass
0.2249	19	5	26	Pass
0.2272	17	4	23	Pass
0.2295	14	4	28	Pass
0.2317	13	4	30	Pass
0.2340	12	4	33	Pass
0.2362	11	4	36	Pass
0.2385	7	4	57	Pass
0.2407	6	4	66	Pass
0.2430	6	4	66	Pass
0.2452	5	4	80	Pass
0.2475	5	4	80	Pass
0.2497	4	3	75	Pass
0.2520	4		75	Pass
0.2542		3	75	Pass
0.2565	3	2	66	Pass
0.2587	3	2	66	Pass
0.2610	3	2	66	Pass
0.2632	3	2	66	Pass
0.2655	4 3 3 3 3 3 3 3	3 2 2 2 2 2 2 2 2	66	Pass
0.2677	3	$\overline{\overline{2}}$	66	Pass
0.2700	3	$\overline{\overline{2}}$	66	Pass
0.2722	3	$\overline{\overline{2}}$	66	Pass
— - -—	-	_		. 5.50

UPS REDMOND 2/1/2017 9:56:48 AM Page 13

Water Quality

Water Quality
Water Quality BMP Flow and Volume for POC #1
On-line facility volume: 0.0859 acre-feet
On-line facility target flow: 0.0436 cfs.
Adjusted for 15 min: 0.0285 cfs.
Adjusted for 15 min: 0.0285 cfs.

UPS REDMOND 2/1/2017 9:56:48 AM Page 14

LID Report

LID Technique	Used for Treatment?	Total Volume Needs Treatment (ac-ft)		Volume	Volume	Percent Volume Infiltrated	Water Quality	Percent Water Quality Treated	Comment
Vault 1 POC		342.43				0.00			
Total Volume Infiltrated		342.43	0.00	0.00		0.00	0.00	0%	No Treat. Credit
Compliance with LID Standard 8% of 2-yr to 50% of 2-yr									Duration Analysis Result = Failed

UPS REDMOND 2/1/2017 9:56:48 AM Page 15

Model Default Modifications

Total of 0 changes have been made.

PERLND Changes

No PERLND changes have been made.

IMPLND Changes

No IMPLND changes have been made.

UPS REDMOND 2/1/2017 9:57:17 AM Page 16

Appendix Predeveloped Schematic

	7 [1	Basin 2.64ac	1			

Mitigated Schematic

77	Basin 1 2.65ac			
\$1	Vault 1			
A1	Vault 1			

Predeveloped UCI File

END ACTIVITY

PRINT-INFO

RUN GLOBAL WWHM4 model simulation END 2009 09 30 3 0 START 1948 10 01 RUN INTERP OUTPUT LEVEL RESUME 0 RUN 1 UNIT SYSTEM 1 END GLOBAL FILES <File> <Un#> <---->*** <-ID-> WDM 26 UPS REDMOND.wdm PreUPS REDMOND.MES MESSU 25 27 PreUPS REDMOND.L61 28 PreUPS REDMOND.L62 POCUPS REDMOND1.dat 30 END FILES OPN SEQUENCE INGRP INDELT 00:15 11 PERLND 12 PERLND COPY 501 DISPLY END INGRP END OPN SEQUENCE DISPLY DISPLY-INFO1 # - # -----Title----->***TRAN PIVL DIG1 FIL1 PYR DIG2 FIL2 YRND 1 Basin 1 MAX 1 2 30 9 END DISPLY-INFO1 END DISPLY COPY TIMESERIES # - # NPT NMN *** 1 1 501 1 1 1 END TIMESERIES END COPY GENER OPCODE # # OPCD *** END OPCODE PARM K *** # END PARM END GENER PERLND GEN-INFO <PLS ><-----Name---->NBLKS Unit-systems Printer *** User t-series Engl Metr *** # - # in out 11 C, Forest, Mod 12 C, Forest, Steep 1 1 1 1 1 27 1 END GEN-INFO *** Section PWATER*** ACTIVITY # - # ATMP SNOW PWAT SED PST PWG PQAL MSTL PEST NITR PHOS TRAC ***
11 0 0 1 0 0 0 0 0 0 0 0 0
12 0 0 1 0 0 0 0 0 0 0

- # ATMP SNOW PWAT SED PST PWG PQAL MSTL PEST NITR PHOS TRAC ********

11 12 END PRINT	0 0 C-INFO	0 0	4 4		0 0	0		0	0	0	0	1	
PWAT-PARM	PWATE CSNO R 0 0		ZFG VC	S VU		VIFW	VIRC 0	VLE 0	INFC 0	HWT	***		
PWAT-PARM <pls> # - # 11 12 END PWAT-</pls>	P ***FOR		LZS	5 5	Part : INFILT 0.08 0.08			S	0.1 0.15		CVARY 0.5 0.5		AGWRC 0.996 0.996
PWAT-PARM <pls> # - # 11 12 END PWAT-PWAT-PARM</pls>	P' ***PET -PARM3 14	0		0	2		NFILD 2 2	·** DE	EPFR 0 0	BÆ	ASETP 0 0		.GWETP 0 0
<pls> # - # 11 12 END PWAT-</pls>	CE	PSC 0.2	028	5N 5	Part 4 NSUR 0.35 0.35		INTFW 6 6		IRC 0.5 0.3		DZETP 0.7 0.7		
PWAT-STAT <pls> # - # 11 12 END PWAT-</pls>	*** In ran *** C	from EPS 0 0	1990 t	o end S 0	of 19	92 (p	at 1-1	.1-95)			** AGWS 1		GWVS 0 0
END PERLND IMPLND GEN-INFO <pls><</pls>	(-Name-		·> U:	nit-sy:	stems	Pri	.nter	***				
# - # END GEN-I *** Secti	NFO			Use		eries out		Metr	***				
ACTIVITY <pls> # - # END ACTIV</pls>	ATMP S							*****	*****	****	****		
PRINT-INF <ils> # - # END PRINT</ils>	***** ATMP S	** Pri NOW IW	.nt-fla NAT SI	ıgs ** ıD IW	***** G IQAL	PIVL *	PYR ****	· * *					
IWAT-PARM <pls> # - # END IWAT-</pls>	IWATE:	R vari TOP V	able m VRS VN	nonthl IN RTL	y parai I	meter ***	value	e flag	,s **	* *			
IWAT-PARM <pls> # - # END IWAT-</pls>	*** L	WATER SUR	input SLSU	info: IR	Part :	2	* RETSC	***					
IWAT-PARM	13												

UPS REDMOND 2/1/2017 9:57:17 AM Page 20

```
<PLS > IWATER input info: Part 3 ***
  # - # ***PETMAX PETMIN
 END IWAT-PARM3
 IWAT-STATE1
   <PLS > *** Initial conditions at start of simulation
   # - # *** RETS SURS
 END IWAT-STATE1
END IMPLND
SCHEMATIC
                   <--Area--> <-Target-> MBLK ***
<-factor-> <Name> # Tbl# ***
<-Source->
<Name> #
Basin 1***
                        1.32 COPY 501 12
1.32 COPY 501 13
1.32 COPY 501 12
1.32 COPY 501 13
PERLND 11
PERLND 11
PERLND 12
PERLND 12
*****Routing*****
END SCHEMATIC
NETWORK
<-Volume-> <-Grp> <-Member-><--Mult-->Tran <-Target vols> <-Grp> <-Member-> ***
END NETWORK
RCHRES
 GEN-INFO
  RCHRES Name Nexits Unit Systems Printer
                                                        * * *
  # - #<----- User T-series Engl Metr LKFG
                                                        * * *
                               in out
                                                        * * *
 END GEN-INFO
 *** Section RCHRES***
   <PLS > ******* Active Sections ******************************
   # - # HYFG ADFG CNFG HTFG SDFG GQFG OXFG NUFG PKFG PHFG ***
 END ACTIVITY
 PRINT-INFO
   <PLS > ******** Print-flags ******** PIVL PYR
   # - # HYDR ADCA CONS HEAT SED GQL OXRX NUTR PLNK PHCB PIVL PYR ********
 END PRINT-INFO
 HYDR-PARM1
   RCHRES Flags for each HYDR Section
       END HYDR-PARM1
 HYDR-PARM2
  # - # FTABNO LEN DELTH STCOR
 END HYDR-PARM2
 HYDR-INIT
  RCHRES Initial conditions for each HYDR section
 END HYDR-INIT
END RCHRES
```

SPEC-ACTIONS END SPEC-ACTIONS FTABLES END FTABLES

EXT SOURCES

<-Volume	->	<member></member>	SsysSgar	<mult>Tran</mult>	<-Target	VO	ls>	<-Grp>	<-Member->	* * *
<name></name>	#	<name> #</name>	tem str	g<-factor->strg	<name></name>	#	#		<name> # #</name>	* * *
WDM	2	PREC	ENGL	1	PERLND	1	999	EXTNL	PREC	
WDM	2	PREC	ENGL	1	IMPLND	1	999	EXTNL	PREC	
WDM	1	EVAP	ENGL	0.76	PERLND	1	999	EXTNL	PETINP	
WDM	1	EVAP	ENGL	0.76	IMPLND	1	999	EXTNL	PETINP	

END EXT SOURCES

EXT TARGETS

MASS-LINK

<volume> <name></name></volume>	<-Grp>	<-Member->< <name> # #<</name>		<target> <name></name></target>	<-Grp>	<-Member->*** <name> # #***</name>
MASS-LIN	K	12				
PERLND	PWATER	SURO	0.083333	COPY	INPUT	MEAN
END MASS	-LINK	12				
MASS-LIN	K	13				
PERLND	PWATER	IFWO	0.083333	COPY	INPUT	MEAN
END MASS	-T.TNK	13				

END MASS-LINK

END RUN

Mitigated UCI File

RUN

```
GLOBAL
 WWHM4 model simulation
                     END 2009 09 30
3 0
 START 1948 10 01
 RUN INTERP OUTPUT LEVEL
 RESUME 0 RUN 1
                                   UNIT SYSTEM 1
END GLOBAL
FILES
<File> <Un#>
           <---->***
<-ID->
WDM
         26
           UPS REDMOND.wdm
MESSU
         25
           MitUPS REDMOND.MES
         27
            Mitups REDMOND.L61
         28
             MitUPS REDMOND.L62
            POCUPS REDMOND1.dat
         30
END FILES
OPN SEQUENCE
   INGRP
                  INDELT 00:15
            16
    PERLND
             17
    PERLND
             18
    PERLND
             12
    IMPLND
             1
1
    RCHRES
    COPY
    COPY
             501
    DISPLY
   END INGRP
END OPN SEQUENCE
DISPLY
 DISPLY-INFO1
   # - #<-----Title----->***TRAN PIVL DIG1 FIL1 PYR DIG2 FIL2 YRND
      Vault 1
 END DISPLY-INFO1
END DISPLY
COPY
 TIMESERIES
  # - # NPT NMN ***
 END TIMESERIES
END COPY
GENER
 OPCODE
  # # OPCD ***
 END OPCODE
              K ***
  #
 END PARM
END GENER
PERLND
 GEN-INFO
  <PLS ><----Name---->NBLKS Unit-systems Printer ***
                           User t-series Engl Metr ***
  # - #
                                  in out
                              C, Lawn, Flat
  17
       C, Lawn, Mod
                           1
                           1
  18
       C, Lawn, Steep
 END GEN-INFO
 *** Section PWATER***
   <PLS > ******** Active Sections **********************
   # - # ATMP SNOW PWAT SED PST PWG PQAL MSTL PEST NITR PHOS TRAC ***
        0 0 1 0 0 0 0 0 0 0 0
               0
                       0
                           0
                               0
                                        0
                                               0
```

```
18 0 0 1 0 0 0 0 0 0 0 0
 END ACTIVITY
 PRINT-INFO
  <PLS > ************ Print-flags ************************ PIVL PYR
  # - # ATMP SNOW PWAT SED PST PWG PQAL MSTL PEST NITR PHOS TRAC ********
     0 0 4 0 0 0 0 0 0 0 0 1 9
         17
  18
 END PRINT-INFO
 PWAT-PARM1
  <PLS > PWATER variable monthly parameter value flags ***
  # - # CSNO RTOP UZFG VCS VUZ VNN VIFW VIRC VLE INFC HWT ***
     17
  18 0
            0 0 0
                      0 0 0 0 0 0
                                              0
 END PWAT-PARM1
 PWAT-PARM2
  <PLS > PWATER input info: Part 2
                               LSUR
  # - # ***FOREST LZSN INFILT
                                                    AGWRC
                                      SLSUR
                                              KVARY
                        0.03
                                       0.05
        0
                                              0.5
                                                    0.996
                  4.5
                                400
  17
             0
                  4.5
                         0.03
                                 400
                                       0.1
                                                0.5
                                                      0.996
                   4.5
                         0.03
                                 400
                                       0.15
                                               0.5
                                                      0.996
  18
             0
 END PWAT-PARM2
 PWAT-PARM3
         PWATER input info: Part 3
  <PLS >
  # - # ***PETMAX PETMIN INFEXP
                               INFILD DEEPFR
                                              BASETP
                                                     AGWETP
 17
        0
                 0
                               2
                                      0
                                              0
                                                     0
             0
                    0
                           2
                                   2
                                          0
                                                 0
                                                         0
 18
                                   2
 END PWAT-PARM3
 PWAT-PARM4
          PWATER input info: Part 4
  <PLS >
                                INTFW
                                      IRC
                                              LZETP ***
  # - #
          CEPSC UZSN NSUR
                                              0.25
  16
          0.1
                  0.25
                         0.25
                                6
                                        0.5
  17
            0.1
                  0.25
                         0.25
                                   6
                                         0.5
                                               0.25
                  0.15
                                              0.25
  18
           0.1
                         0.25
                                   6
                                        0.3
 END PWAT-PARM4
 PWAT-STATE1
  <PLS > *** Initial conditions at start of simulation
        ran from 1990 to end of 1992 (pat 1-11-95) RUN 21 ***
      # *** CEPS SURS UZS IFWS LZS AGWS
                                                      GWVS
                 0
                         0
                                 0
                                         2.5
                                               1
  16
             0
                                                        0
  17
             0
                    0
                           0
                                   0
                                         2.5
                                                 1
                                                         0
                           0
                    0
                                   Ω
                                         2.5
  18
             0
                                                 1
                                                         0
 END PWAT-STATE1
END PERLND
IMPLND
 GEN-INFO
  <PLS ><----Name----> Unit-systems Printer ***
                      User t-series Engl Metr ***
                           in out ***
                        1 1 1
                                  27 0
      PARKING/MOD
 END GEN-INFO
 *** Section IWATER***
 ACTIVITY
  # - # ATMP SNOW IWAT SLD IWG IQAL 12 0 0 1 0 0 0
 END ACTIVITY
 PRINT-INFO
  <ILS > ******* Print-flags ******* PIVL PYR
```

```
# - # ATMP SNOW IWAT SLD IWG IQAL ********
12 0 0 4 0 0 0 1 9
 END PRINT-INFO
  IWAT-PARM1
   <PLS > IWATER variable monthly parameter value flags ***
  END IWAT-PARM1
 IWAT-PARM2
  END IWAT-PARM2
 IWAT-PARM3
  * * *
  # - # ***PETMAX PETMIN
12 0 0
 END IWAT-PARM3
 IWAT-STATE1
   <PLS > *** Initial conditions at start of simulation
   # - # *** RETS SURS
        0
                     0
 END IWAT-STATE1
END IMPLND
SCHEMATIC
                       <--Area--> <-Target-> MBLK *** <-factor-> <Name> # Tbl# ***
<-Source->
<Name> #
Basin 1***
                             0.27
                                    RCHRES 1
PERLND 16
                                                  2
                                    RCHRES 1
RCHRES 1
RCHRES 1
RCHRES 1
RCHRES 1
RCHRES 1
PERLND 16
PERLND 17
PERLND 17
                             0.27
                                                  3
                                                  2
                             0.17
                             0.17
PERLND
                             0.15
      18
PERLND 18
                             0.15
                                                  3
                                   RCHRES 1
IMPLND 12
                             2.06
*****Routing****
                            0.27 COPY 1 12
0.17 COPY 1 12
0.15 COPY 1 12
2.06 COPY 1 15
0.27 COPY 1 13
0.17 COPY 1 13
0.15 COPY 1 13
1 COPY 501 16
PERLND 16
PERLND 17
PERLND 18
IMPLND 12
PERLND 16
PERLND 17
PERLND 18
RCHRES 1
END SCHEMATIC
NETWORK
<-Volume-> <-Grp> <-Member-><--Mult-->Tran <-Target vols> <-Grp> <-Member-> ***
<-Volume-> <-Grp> <-Member-><--Mult-->Tran <-Target vols> <-Grp> <-Member-> ***
END NETWORK
RCHRES
 GEN-INFO
          Name Nexits Unit Systems Printer
   RCHRES
   # - #<----><---> User T-series Engl Metr LKFG
                                in out
1 1 1 28 0 1
                                   in out
   1 Vault 1
                            1
```

```
END GEN-INFO
 *** Section RCHRES***
 ACTIVITY
   <PLS > ********* Active Sections *********************
   # - # HYFG ADFG CNFG HTFG SDFG GQFG OXFG NUFG PKFG PHFG ***
       1 0 0 0 0 0 0 0 0
 END ACTIVITY
 PRINT-INFO
   <PLS > ******** Print-flags ******** PIVL PYR
   # - # HYDR ADCA CONS HEAT SED GQL OXRX NUTR PLNK PHCB PIVL PYR ********
1 4 0 0 0 0 0 0 0 0 1 9
 HYDR-PARM1
   RCHRES Flags for each HYDR Section
   END HYDR-PARM1
 HYDR-PARM2
  # - # FTABNO LEN DELTH STCOR KS DB50
 <------><-----><-----><----->
  1 1 0.02 0.0 0.0 0.5 0.0
 END HYDR-PARM2
 HYDR-INIT
   RCHRES Initial conditions for each HYDR section
 4.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0
 END HYDR-INIT
END RCHRES
SPEC-ACTIONS
END SPEC-ACTIONS
FTABLES
 FTABLE
  92 4
    Depth Area Volume Outflowl Velocity Travel Time***
     (ft) (acres) (acre-ft) (cfs) (ft/sec) (Minutes)***
 0.000000 0.153954 0.000000 0.000000

0.076556 0.153954 0.011786 0.007966

0.153111 0.153954 0.023572 0.011265

0.229667 0.153954 0.035358 0.013797

0.306222 0.153954 0.047144 0.015931
 0.382778 0.153954 0.058930 0.017812
 0.459333 0.153954 0.070716 0.019512
 0.535889 0.153954 0.082502 0.021075
 0.612444 0.153954 0.094288 0.022530
 0.689000 0.153954 0.106074 0.023897
 0.765556 0.153954 0.117861 0.025190
 1.071778 0.153954 0.165005 0.029805
 1.148333 0.153954 0.176791 0.030851
 1.224889 0.153954 0.188577 0.031863
 1.301444 0.153954 0.200363 0.032843
 1.378000 0.153954 0.212149 0.033795
 1.454556 0.153954 0.223935 0.034721
 1.531111 0.153954 0.235721 0.035623
1.607667 0.153954 0.247507 0.036503
1.684222 0.153954 0.259293 0.037362
 1.760778 0.153954 0.271079 0.038202
 1.837333 0.153954 0.282865 0.039024
 1.913889 0.153954 0.294651 0.039828
```

EXT SOURCES

UPS REDMOND 2/1/2017 9:57:17 AM Page 27

	r> SsysSgap <mult>Tran # tem strg<-factor->strg ENGL 1 ENGL 1 ENGL 0.76 ENGL 0.76</mult>	<name> # #</name>	<pre></pre>
END EXT SOURCES			
			ne> tem strg strg*** ENGL REPL ENGL REPL ENGL REPL
<name> MASS-LINK</name>	<-Member-> <mult> <name> # #<-factor-> 2</name></mult>	<name></name>	<-Grp> <-Member->***
PERLND PWATER END MASS-LINK	SURO 0.083333 2	RCHRES	INFLOW IVOL
MASS-LINK PERLND PWATER END MASS-LINK	3 IFWO 0.083333	RCHRES	INFLOW IVOL
MASS-LINK IMPLND IWATER END MASS-LINK	5 SURO 0.083333 5	RCHRES	INFLOW IVOL
MASS-LINK PERLND PWATER END MASS-LINK	12 SURO 0.083333 12	СОРУ	INPUT MEAN
MASS-LINK PERLND PWATER END MASS-LINK	13 IFWO 0.083333 13	СОРУ	INPUT MEAN
MASS-LINK IMPLND IWATER END MASS-LINK	15 SURO 0.083333 15	COPY	INPUT MEAN
MASS-LINK RCHRES ROFLOW END MASS-LINK	16 16	COPY	INPUT MEAN

END MASS-LINK

END RUN

Predeveloped HSPF Message File

Mitigated HSPF Message File

Disclaimer

Legal Notice

This program and accompanying documentation are provided 'as-is' without warranty of any kind. The entire risk regarding the performance and results of this program is assumed by End User. Clear Creek Solutions Inc. and the governmental licensee or sublicensees disclaim all warranties, either expressed or implied, including but not limited to implied warranties of program and accompanying documentation. In no event shall Clear Creek Solutions Inc. be liable for any damages whatsoever (including without limitation to damages for loss of business profits, loss of business information, business interruption, and the like) arising out of the use of, or inability to use this program even if Clear Creek Solutions Inc. or their authorized representatives have been advised of the possibility of such damages. Software Copyright © by : Clear Creek Solutions, Inc. 2005-2017; All Rights Reserved.

Clear Creek Solutions, Inc. 6200 Capitol Blvd. Ste F Olympia, WA. 98501 Toll Free 1(866)943-0304 Local (360)943-0304

www.clearcreeksolutions.com

UPS REDMOND 2/1/2017 9:57:17 AM Page 31